





report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE CDTI
Colour	Grey
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	205 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-19

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-29
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #12		2023-09-28 13:36
MOT test n	umber	669388806781
Result		✓ Passed
Next expir	y date	2024-09-29
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #11	2022-09-30 15:36
MOT test number	604117193305
Result	✓ Passed
Advice Front front wipers smearing	

MOT #10	2021-09-25 15:34
MOT test number	288949976376
Result	✓ Passed
MOT #9	2020-09-28 12:28
MOT test number	836039813555
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

MT61LGJ report date: 2024-03-28

× Failed

MOT #8 2019-12-16 16:04

MOT test number 463577312976

Result Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7 2019-12-16 13:09

MOT test number 831076034217

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6 2019-01-02 15:25

MOT test number 199262478736

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing 235/50R19 (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 235/50R19 (5.2.3 (d) (ii))

MOT #5 2018-01-05 11:09

MOT test number 357291296679

Result

Passed

Advice Offside Front Tyre worn close to the legal limit Outer edge (4.1.E.1)

Advice Oil leak

CarCheck.co.uk page 4/12



Result

MT61LGJ report date: 2024-03-28

✓ Passed

MOT test number

Result

Fail Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit Outer edge (4.1.E.1)

Advice Oil leak

Autrec	
MOT #3	2016-12-28 12:25
MOT test number	207608550348
Result	✓ Passed
MOT #2	2016-01-21 09:39
MOT test number	409054550343
Result	✓ Passed
MOT #1	2015-01-20 15:34
MOT test number	637440825063

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
_	

Damage 2

Date Category

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-01-27
Last registration	2023-09-28
Complete history	See info



Registration #1	2012-01-27	14 mi
Registration #2	2015-01-20	15.997 mi
Registration #3	2016-01-21	18.307 mi
Registration #4	2016-12-28	20.964 mi
Registration #5	2018-01-04	23.285 mi
Registration #6	2018-01-05	23.286 mi
Registration #7	2019-01-02	25.377 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	113063K

CarCheck.co.uk page 12/12