



TOYOTA

LX59JHV

report date: 2024-03-28

General information

Make	TOYOTA
Model	YARIS
Colour	Black
Year of manufacture	2010
Gearbox	-

Engine & fuel consumption

Engine capacity	1.298 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-24
Pictures	25
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-01-09
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	5

MOT #7 2024-01-10 13:53**MOT test number** 408025269170**Result** Passed**Next expiry date** 2025-01-09**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2024-01-10 13:53**MOT test number** 819230377554**Result** Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2022-09-08 13:47**MOT test number** 850712976423**Result** Passed

**MOT #4**

2022-09-08 10:55

MOT test number

582534736887

Result**✗ Failed**

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

MOT #3

2021-09-18 13:58

MOT test number

421934929948

Result**✓ Passed**

Minor Front Headlamp lens slightly defective both (4.1.1 (b) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #2

2020-09-18 10:21

MOT test number

413735718535

Result**✓ Passed****MOT #1**

2020-04-15 14:54

MOT test number

962973069522

Result**✓ Passed**



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
9 January 2025

Tax status		Valid until 1 January
Days left		247
MOT expiry date		9 January 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	LX59JHV
Plate since	2019-03-28
Current registration	LX59JHV
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2020-04-15
Last registration	2024-01-10
Complete history	See info



Registration #1	2020-04-15	24.443 mi
Registration #2	2020-09-18	24.461 mi
Registration #3	2021-09-18	49.628 mi
Registration #4	2022-09-18	55.577 mi
Registration #5	2023-09-18	55.577 mi
Registration #6	2023-09-18	55.577 mi
Registration #7	2023-09-18	55.577 mi
Registration #8	2023-09-18	55.577 mi

More info >

Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Additional information

Number of seats	5
Engine number	NOT KNOWN