



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2



Date	2021-09-15
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-06
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-19
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	11
Total items failed	15

MOT #14	2023-08-21 12:38
MOT test number	414589381935
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2022-09-08 15:44
MOT test number	443995886558
Result	✓ Passed

**MOT #12**

2022-09-08 07:04

MOT test number

148614461188

Result

✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Undertray insecure**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11**

2021-09-20 15:26

MOT test number

216969451412

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2020-12-04 12:34

MOT test number

402164745449

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2019-11-29 14:19

MOT test number

290232364841

Result

✓ Passed

**MOT #8** 2019-11-29 09:56**MOT test number** 685123222964**Result** ✗ Failed

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #7 2018-12-05 14:45**MOT test number** 545105339670**Result** ✓ Passed

- Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #6 2017-12-07 09:37**MOT test number** 642716526843**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2016-11-24 09:15**MOT test number** 400426183420**Result** ✓ Passed**MOT #4** 2015-12-03 12:56**MOT test number** 902060277287**Result** ✓ Passed

**MOT #3** 2015-12-03 12:56**MOT test number** 970078160303**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2014-12-10 12:38**MOT test number** 888034144321**Result** ✓ Passed**MOT #1** 2014-12-10 11:24**MOT test number** 276754444333**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-31
Last registration	2023-08-21
Complete history	See info



Registration #1	2012-01-31	26 mi
Registration #2	2014-12-10	37.784 mi
Registration #3	2014-12-10	37.784 mi
Registration #4	2015-12-03	50.076 mi
Registration #5	2015-12-03	50.076 mi
Registration #6	2016-11-24	59.801 mi
Registration #7	2017-12-07	66.247 mi
Registration #8	2018-12-05	72.547 mi
Registration #9	2019-11-29	78.601 mi
Registration #10	2020-05-20	85.377 mi
Registration #11	2020-05-20	85.377 mi
Registration #12	2020-05-20	85.377 mi
Registration #13	2020-05-20	85.377 mi
Registration #14	2020-05-20	85.377 mi
Registration #15	2020-05-20	85.377 mi
Registration #16	2020-05-20	85.377 mi
Registration #17	2020-05-20	85.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1958881