





report date: 2024-03-29

## General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Blue
Year of manufacture	2013
Top speed	140 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



BN62OUJ

report date: 2024-03-29

## Internet history

### Entry 2

Date 2021-10-06

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-10-05
Pictures	25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

BN62OUJ report date: 2024-03-29

MOT expiry date	2024-11-15
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #8	2023-11-09 08:28
MOT test number	714668073044
Result	✓ Passed
Next expiry date	2024-11-15

MOT #7	2022-11-14 08:53
MOT test number	296248211155
Result	<b>✓</b> Passed
Advice Nearside Front ALLOY DAMAGED	

MOT #6	2021-11-16 12:56
MOT test number	998746544495
Result	✓ Passed

MOT #5	2020-09-18 09:58
MOT test number	463087033226
Result	<b>✓</b> Passed
Minor Central Lower Windscreen damaged but not adversely aff	ecting driver's view (3.2 (a) (i))

MOT #4	2019-04-02 14:31
MOT test number	972186351033
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT #3		2018-04-02 14:15
MOT test	number	471564709766
Result		<b>✓</b> Passed
MOT #2		2017-03-30 13:17
MOT test	number	858911739667
Result		✓ Passed
Advice	Nearside Front tyre has cuts outer wall	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Nail in tyre	
Advice	Engine covers/under trays fitted at time of test	
Advice	Rear Inner Brake pad(s) wearing thin (3.5.1g)	

MOT #1		2016-03-31 12:02
MOT test	number	371072947345
Result		<b>✓</b> Passed
Advice	Under trays fitted at time of test	
Advice	Nearside Front tyre has a deep cut on the outer wall	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	15 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



BN62OUJ

report date: 2024-03-29

### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



BN62OUJ

report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NK SIZ
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-01-28
Last registration	2023-11-09
Complete history	See info



Registration #1	2013-01-28	20 mi
Registration #2	2016-03-31	36.138 mi
Registration #3	2017-03-30	37.793 mi
Registration #4	2018-04-02	53.310 mi
Registration #5	2019-04-02	62.937 mi
Registration #6	2020-09-18	74.376 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1696 kg
Max. allowed weight	2200 kg

## Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2
Engine number 1305305