



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ADAM ENERGISED
Colour	Black
Year of manufacture	2017
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 4

Date 2021-10-03

Pictures 27

Listing price [View report](#)




source: yesauto.com

Entry 3

Date 2021-09-20

Pictures 28

Listing price [View report](#)




source: autotrader.co.uk

Entry 2

Date 2021-09-19

Pictures 28


Listing price [View report](#)



source: autotrader.co.uk

Entry 1

Date 2021-09-19



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	4

MOT #7	2024-03-06 10:44
MOT test number	304599063548
Result	✓ Passed
Next expiry date	2025-03-07
Advice	Clutch pedal rubber missing
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Shock absorbers has light misting of oil All shocks (5.3.2 (b))

MOT #6	2024-03-01 16:18
MOT test number	515326212465
Result	✗ Failed
Advice	Shock absorbers has light misting of oil All shocks (5.3.2 (b))
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Brake pedal anti-slip provision missing (1.1.2 (c))
Advice	Clutch pedal rubber missing
Fail	Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #5**

2023-02-24 08:39

MOT test number

937541289846

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #4**

2022-03-02 08:30

MOT test number

251065251586

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #3**

2022-03-02 08:30

MOT test number

628565480385

Result

✗ Failed

Advice Offside Front Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2**

2021-03-08 13:44

MOT test number

981859508759

Result

✓ Passed



MOT #12020-02-11 13:47

MOT test number630437524716

Result

✓ Passed

- Minor

Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-03-01
Last registration	2024-03-06
Complete history	See info



Registration #1	2017-03-01	27 mi
Registration #2	2020-02-11	19.440 mi
Registration #3	2021-03-08	22.751 mi
Registration #4	2022-03-01	25.277 mi
Registration #5	2023-03-01	28.277 mi
Registration #6	2024-03-01	31.277 mi
Registration #7	2025-03-01	34.277 mi
Registration #8	2026-03-01	37.277 mi
Registration #9	2027-03-01	40.277 mi
Registration #10	2028-03-01	43.277 mi
Registration #11	2029-03-01	46.277 mi
Registration #12	2030-03-01	49.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1966 mm
Height	1483 mm
Length	3698 mm
Wheel base	2311 mm
Kerb weight	1011 kg
Max. allowed weight	1470 kg

Additional information

Fuel tank capacity	38 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	B12XER -19NN8638LWD