





report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE N-TEC
Colour	Silver
Year of manufacture	2011
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	128 Nm at 3.200 rpm
Engine capacity	1.386 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-05-23

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT evenimy date	2022 00 00
MOT expiry date	2023-08-09
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	25
Total items failed	5

MOT #13	2022-08-10 09:52
MOT test number	822054648863
Result	✓ Passed
Next expiry date	2023-08-09
Advice Rear Tyre worn close to legal limit/worn on edge Both worn close to legal limit (5.2.3 (e))	

MOT #12	2021-05-21 12:55
MOT test number	776541785491
Result	✓ Passed

MOT #11	2021-05-20 12:12
MOT test number	514255078012
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



GJ61LDZ

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

MOT test number

Result

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT test number

Result

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #7

MOT test number

Result

Advice

Both inner tie rods have play

Rear exhaust bracket rusty

CarCheck.co.uk page 4/13



MOT test number

Result

Advice Both inner tie rods have play

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Rear exhaust bracket rusty

 MOT #5
 2017-09-08 14:46

 MOT test number
 344646531682

 Result
 ✓ Passed

 MOT #4
 2017-09-01 09:05

 MOT test number
 244386823709

 Result
 X Failed

 Fail
 Front front brake excessively fluctuating (3.7.B.3)

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



Advice

Advice

GJ61LDZ report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice

Nearside Front Tyre worn close to the legal limit Outer portion (4.1.E.1)

Advice

Brake disc worn, pitted or scored, but not seriously weakened Both front brake disc's are slightly worn and lipped (3.5.1i)

Offside Front Brake pad(s) wearing thin (3.5.1g)

Offside Front Tyre worn close to the legal limit outer portion (4.1.E.1)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	9 August 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-10
Last registration	2022-08-10
Complete history	See info



Registration #1	2011-09-10	25 mi
Registration #2	2014-09-10	28.423 mi
Registration #3	2015-09-08	48.305 mi
Registration #4	2016-09-09	56.460 mi
Registration #5	2017-09-01	64.330 mi
Registration #6	2017-09-08	64.412 mi
Registration #7	2018-09-08	71.234 mi
Registration #8	2018-09-08	71.234 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1691 mm
Height	1550 mm
Length	4100 mm
Wheel base	2600 mm
Max. allowed weight	1546 kg

Additional information

Fuel tank capacity	46 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

CR14-309681