



report date: 2024-03-28

General information

Make	MAZDA
Model	6 TS2
Colour	Blue
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	184 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #17	2021-11-22 14:41
MOT test number	208962389320
Result	✓ Passed
Next expiry date	2022-11-23
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Underside covered by trays

MOT #16	2020-11-24 12:36
MOT test number	737821602446
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view chip in centre of screen (3.2 (a) (i))
Advice	After market fuel cap fitted but still lockable
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))

MOT #15	2020-11-18 13:16
MOT test number	712068254780
Result	✗ Failed
Fail	Front Position lamp not working n/s & o/s (4.2.1 (a) (ii))
Advice	After market fuel cap fitted but still lockable
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))
Fail	Offside Front Headlamp aim too low (4.1.2 (a))
Minor	Windscreen damaged but not adversely affecting driver's view chip in centre of screen (3.2 (a) (i))

MOT #14	2019-09-16 14:09
MOT test number	152263375301
Result	✓ Passed

**MOT #13**

2018-09-17 11:26

MOT test number

902555669883

Result

✓ Passed

- Advice** Nearside Rear Light lens cracked
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Temporary fuel sealing device fitted
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

2018-09-17 08:59

MOT test number

812609349587

Result

✗ Failed

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Light lens cracked
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Advice** Temporary fuel sealing device fitted
- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11

2017-09-15 14:15

MOT test number

180614681153

Result

✓ Passed

**MOT #10** 2017-09-15 07:55**MOT test number** 700392011052**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Exhaust has a minor leak of exhaust gases rear centre pipe (7.1.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2016-09-12 09:05**MOT test number** 783100458477**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8** 2015-09-07 16:11**MOT test number** 758017734590**Result** ✓ Passed**MOT #7** 2015-09-07 08:48**MOT test number** 199880740943**Result** ✗ Failed**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords wall (4.1.D.1a)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-09-16 14:24**MOT test number** 888669054268**Result** ✓ Passed**MOT #5** 2014-08-21 11:57**MOT test number** 439903734253**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Headlamp aim too high (1.8)**MOT #4** 2013-09-10 16:53**MOT test number** 306833353208**Result** ✓ Passed**MOT #3** 2013-09-10 09:31**MOT test number** 458293853245**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2012-09-21 10:00
MOT test number	695695762298
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-07-05 15:06
MOT test number	545066681197
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	GR08FMC
Plate since	2019-09-28
Current registration	GR08FMC
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-08-08
Last registration	2021-11-22
Complete history	See info



Registration #1	2008-08-08	15 mi
Registration #2	2011-07-05	30.065 mi
Registration #3	2012-09-21	41.613 mi
Registration #4	2013-09-10	52.703 mi
Registration #5	2013-09-10	52.703 mi
Registration #6	2014-08-21	64.406 mi
Registration #7	2014-09-16	65.725 mi
Registration #8	2015-09-07	78.558 mi
Registration #9	2015-09-07	78.559 mi
Registration #10	2016-09-12	88.464 mi
Registration #11	2016-09-12	88.464 mi
Registration #12	2016-09-12	88.464 mi
Registration #13	2016-09-12	88.464 mi
Registration #14	2016-09-12	88.464 mi
Registration #15	2016-09-12	88.464 mi
Registration #16	2016-09-12	88.464 mi
Registration #17	2016-09-12	88.464 mi
Registration #18	2016-09-12	88.464 mi
Registration #19	2016-09-12	88.464 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10448398