





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	White
Year of manufacture	2014
Top speed	146 mph
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	200 BHP
Max. torque	275 Nm at 1.700 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-05-26

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

### MOT history

MOT expiry date	2025-01-03
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	25
Total items failed	8

MOT #13		2024-01-04 09:20
MOT test	number	663781420872
Result		✓ Passed
Next expi	ry date	2025-01-03
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply o	r cords (5.2.3 (d) (i))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))	

MOT #12	2024-01-04 09:20
MOT test number	250217850176
Result	<b>★</b> Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice Oil leak, but not	excessive Engine (8.4.1 (a) (i))
Pass with rectification	Nearside Headlamp insecure (4.1.1 (c))
Advice Nearside Front T	Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/13



× Failed

**MOT #11** 2022-12-29 10:18

MOT test number 383626502469

**Result** ✓ Passed

**Advice** Tpms indicates low tyre pressures

Advice Rear brake pads 4mm/inner brake discs lightly corroded

**Advice** Front inner brake discs worn/corroded/pads okay

**MOT #10** 2022-12-29 10:18

MOT test number 868528725801

Advice Front inner brake discs worn/corroded/pads okay

**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Tpms indicates low tyre pressures

Advice Rear brake pads 4mm/inner brake discs lightly corroded

Pass with rectification Exhaust carbon monoxide content after 2nd fast idle exceeds default limits

(8.2.1.2 (b))

Result

MOT #9 2021-12-30 13:00

**MOT test number** 405544576152

Result \( \sqrt{Passed} \)

**Advice** Engine oil leak evident

**Advice** Rear brake pads 4mm

**Advice** Front lower wishbones rear bushes perished

CarCheck.co.uk page 4/13



Pass with rectification

DX14ZZM

report date: 2024-03-28

2021-12-30 13:00 **MOT #8** 556414184084 **MOT test number** Result × Failed Pass with rectification Nearside Front Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Advice Rear brake pads 4mm **Advice** Front lower wishbones rear bushes perished Pass with rectification Offside Front Headlamp light intensity severely reduced (4.1.4 (a)) Pass with rectification Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) **Advice** Engine oil leak evident

Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))

MOT #7	2020-12-22 17:25
MOT test number	248108857409
Result	<b>✓</b> Passed
MOT #6	2020-02-03 11:20
MOT test number	554363133012
Result	<b>✓</b> Passed
MOT #5	2019-06-07 15:08
MOT test number	438379653259
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

**MOT #4** 2019-06-06 09:03

**MOT test number** 966312758216

Result X Failed

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-06-06 11:54

**MOT test number** 904748071358

**Result** ✓ Passed

MOT #2 2018-03-08 12:42

MOT test number 803282320385

Result \( \sqrt{Passed} \)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Windscreen wipers smearing

**Advice** Engine management lamp illuminated

**Advice** Damage to offside outer sill

**MOT #1** 2017-03-29 08:30

MOT test number 218455636211

**Advice** Both front tyres getting low and wearing on inner edge

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	3 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NIS UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-31
Last registration	2024-01-04
Complete history	See info



Registration #1	2014-03-31	28 mi
Registration #2	2017-03-29	47.198 mi
Registration #3	2018-03-08	64.383 mi
Registration #4	2018-06-06	65.625 mi
Registration #5	2019-06-06	91.101 mi
Registration #6	2019-06-07	91.111 mi
Registration #7	2020-02-03	106.316 mi
Registration #8	2020-12-22	111.173 mi
Registration #9		11.777 es
Registration #10		0.00 44
Registration #11		0.07 mi
Registration #12		0.00 44
Registration #13		0.07 mi
Registration #14		11.771 46
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

### Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Wheel base	2612 mm
Kerb weight	1411 kg
Max. allowed weight	1780 kg

### Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

**Engine number** FKAP2022085