





report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 X-EC
Colour	Black
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F



CarCheck.co.uk page 1/12



LM12EHV

report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-10
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #12		2023-12-11 10:00
MOT test	number	361089281381
Result		✓ Passed
Next expi	ry date	2024-12-10
Advice	Rear bumper trim adrift becoming insecure	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #11	2023-12-08 10:34
MOT test number	251685646393
Result	X Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Rear bumper trim adrift becoming insecure	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #10	2022-12-09 09:02
MOT test number	311621374295
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/12



MOT #9 2021-12-09 09:01

MOT test number 715477950966

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2020-12-10 13:45

MOT test number 121858235665

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #7 2020-03-26 13:03

MOT test number 230046182697

Result \rightarrow Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge inside edge of tread (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inside edge of tread (5.2.3 (e))

MOT #6 2019-04-01 10:53

MOT test number 740671798294

Result Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2018-03-22 10:35

MOT test number 813813661960

Result
✓ Passed

Advice Offside Rear tyre cracked and perished

CarCheck.co.uk page 4/12



LM12EHV

report date: 2024-03-28



MOT #3	2016-09-28 10:21
MOT test number	966699372003
Result	✓ Passed
MOT #2	2016-09-28 10:15
MOT test number	774566921308
Result	X Failed
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #1	2015-09-02 15:23
MOT test number	119897969579
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



LM12EHV

report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-30
Last registration	2023-12-11
Complete history	See info



Registration #1	2012-03-30	6 mi
Registration #2	2015-09-02	12.852 mi
Registration #3	2016-09-28	18.024 mi
Registration #4	2016-09-28	18.024 mi
Registration #5	2018-03-22	27.755 mi
Registration #6	2018-03-22	27.755 mi
Registration #7	2019-04-01	37.292 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1555 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1240 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1651017

CarCheck.co.uk page 12/12