





General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Black
Year of manufacture	2007
Top speed	149 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	220 g/km
CO2 label	К





Internet history

Entry 1

Date Pictures 2021-06-28

12

Listing price

View report



source: autotrader.co.uk





MOT history

MOT expiry date	2022-04-22
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	28
Total items failed	16

MOT #22	2021-04-23 10:38
MOT test number	573245758022
Result	✓ Passed
Next expiry date	2022-04-22





MOT #21	2020-10-21 13:29
MOT test	number 151538433504
Result	× Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
MAJOR	Electronic parking brake warning indicates a malfunction (1.1.6 (e))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
MAJOR rear arm (2	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt 5.3.4 (b) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))
DANGER	OUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Windscreen washer not working (3.5 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
MAJOR front arm	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #20	2019-01-11 11:47
MOT test number	995825819363
Result	✓ Passed
Advice Rear Brake lever pivot slightly tight (1.1.1 (a))	





MOT #19	2017-10-20 08:33
MOT test number	535056572112
Result	✓ Passed
MOT #18	2016-10-13 13:56
MOT test number	228178811697
Result	✓ Passed
NOT #17	
MOT #17 MOT test number	2015-09-22 17:04 885592663802
Result	✓ Passed
Result	
MOT #16	2015-09-14 08:20
MOT test number	270668912911
Result	🗙 Failed
Fail Parking brake: efficiency below requirements (3.7.B.7)	
FailNearside Rear position lamp(s) not working (1.1.A.3b)	
Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	
Fail Electronic parking brake warning indicates a malfunction (3.1.7)	
FailOffside rear brake recording little or no effort (3.7.B.5a)	
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
FailNearside Front Wheel stud(s) missing (4.2.A.1e)	
Fail Electronic stability system warning lamp indicates a fault (3.4.1c)	
Fail Nearside rear brake recording little or no effort (3.7.B.5a)	





MOT #15		2014-08-14 14:08
MOT test numb	er	729296324219
Result		✓ Passed
Advice Near	side Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear	brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Offsi	de Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #14	2014-08-14 09:13
MOT test number	695406724201
Result	🗙 Failed
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
FailRear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
FailFront Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #13	2014-03-25 15:11
MOT test number	829274684039
Result	✓ Passed
Advice Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)	





🗸 Passed

MOT #12	2014-03-22 11:49
MOT test number	695441684050
Result	🗙 Failed
 Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) Advice Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2) 	
MOT #11	2013-03-21 10:15
MOT test number	238650983024

Result

MOT #10		2013-03-21 10:15
MOT test number		298860583089
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	

MOT #9		2012-02-28 15:04
MOT test	number	529039752062
Result		✓ Passed
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A'	(8.3.1d)

MOT #8	2012-02-06 14:48
MOT test number	279767032054
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2011-02-28 11:00
MOT test number	366079851065
Result	✓ Passed





МОТ #6	2010-08-23 14:50
MOT test number	933345530243
Result	✓ Passed
MOT #5	2010-02-25 10:01
MOT test number	654846350030
Result	✓ Passed
MOT #4	2009-09-02 12:22
MOT test number	794455749202
Result	✓ Passed
MOT #3	2009-02-20 14:51
MOT test number	141321159494
Result	✓ Passed
MOT #2	2008-09-11 16:23
MOT test number	202435458290
Result	✓ Passed
MOT #1	2008-02-18 15:26
MOT test number	844749548049
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



KT07JRV report date: 2024-03-28

Tax & MOT check

X Untaxed Tax expired: 19 July 2021	X MOT Expired: 22 April 2022
Tax status	Expired at 19 July 2021
Days left	1015 days too late
MOT expiry date	22 April 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-06-28
Last registration	2021-04-23
Complete history	See info



2007-06-28	20 mi
2008-02-18	9.423 mi
2008-09-11	17.926 mi
2009-02-20	26.378 mi
2009-09-02	34.058 mi
2010-02-25	43.252 mi
2010-08-23	54.391 mi
2011-02-28	61.211 mi
2012-02-06	68.368 mi
2012-02-28	69.497 mi
2013-03-21	78.649 mi
2014-03-22	88.124 mi
	11.777 esi
	11.117 esi
	11.117 esi
	11.777 esi
	11.777 esi
	11.777 esi
	11.117 esi
	11.777 esi
	11.117 est
	2008-02-18 2008-09-11 2009-09-02 2009-09-02 2010-02-25 2010-08-23 2011-02-28 2012-02-06 2012-02-28 2013-03-21 2014-03-22

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg
Additional information	
Additional information Fuel tank capacity	90 l
	90 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4