





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 270 LIMITED LR P/V
Colour	Black
Year of manufacture	2014
Top speed	98 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	330 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	1



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

E to the	M3. F	1
EML	I V	т.

Entry 1	
Date	2021-11-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	18
Total items failed	5

MOT #9	2023-05-02 16:01
MOT test number	742420558805
Result	✓ Passed
Next expiry date	2024-05-01
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	lamps or light sources

MOT #8	2022-04-07 16:01
MOT test number	889344192255
Result	√ Passed
MOT #7	2021-08-20 13:09
MOT test number	106204098961
Result	✓ Passed
Minor Nearside Registration plate lamp inoperative in the case of multiple (b) (i))	ltiple lamps or light sources (4.7.1

CarCheck.co.uk page 3/12



(b) (i))

BP14BYF

report date: 2024-03-28

2021-08-19 08:23 **MOT** #6 155701031182 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 Minor

MOT #5	2020-08-17 16:08
MOT test number	184004234275
Result	✓ Passed

	•
MOT #4	2020-08-17 08:12
MOT test number	732487317114
Result	X Failed
Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

MOT #3	2019-08-19 09:53
MOT test number	993849975621
Result	✓ Passed
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	excessive movement
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	n excessive movement

CarCheck.co.uk page 4/12



Advice

BP14BYF

report date: 2024-03-28

MOT #2 2018-08-20 11:56 **MOT test number** 422575393837 Result ✓ Passed **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Engine stabiliser mount worn **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1		2017-08-30 10:54
MOT test	number	575619402229
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



BP14BYF report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	1 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

$\overline{}$	ner	<u> </u>	L
()\\\	ner	nıs	rorv

, ,		
For how long did the current and previous owner(s) have this FORD? How many owners defined the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK NEW	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-08-05
Last registration	2023-05-02
Complete history	See info



Registration #1	2014-08-05	25 mi
Registration #2	2017-08-30	35.761 mi
Registration #3	2018-08-20	45.663 mi
Registration #4	2019-08-19	57.752 mi
Registration #5	2020-08-17	67.952 mi
Registration #6	2020-08-17	67.952 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	2933 mm
Kerb weight	1817 kg
Max. allowed weight	2700 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	3 page 12/

Number of axles 2

Engine number EP67550