





report date: 2024-03-28

General information

Make	BMW
Model	525 525I M SPORT
Colour	Silver
Year of manufacture	2005
Top speed	152 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	215 BHP
Max. torque	250 Nm at 2.750 rpm
Engine capacity	2.497 cc
Cylinders	6
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	210 g/km
CO2 label	K



CarCheck.co.uk page 1/16



Internet history

Entry 3

Date 2021-10-27

8 **Pictures**

Listing price View report









source: cargurus.co.uk

Entry 2

Date	2021-10-26
------	------------

Pictures 8

Listing price View report









source: autotrader.co.uk

Entry 1

Date	2021-07-30

Pictures 31

Listing price View report









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-03
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	34
Total items failed	21

MOT #24	2024-04-03 15:54
MOT test number	269044754148
Result	✓ Passed
Next expiry date	2025-04-03
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #2	3	2024-04-02 10:09
MOT tes	t number	367445537514
Result		X Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Fail (a))	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's sp	pecified limits (8.2.1.2
Fail (5.2.3 (d	Nearside Front Tyre has a cut in excess of the requirements deep enough to real) (i))	ch the ply or cords
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Nearside Rear Outer Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/16



MOT #22		2023-03-24 16:41
MOT test	number	478145266838
Result		✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Headlamp has a product on the lens but not seriously reducing light ou	tput (4.1.4 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive n	novement (5.3.4 (a)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light of	output (4.1.4 (b))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.1	L4 (a) (ii))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4

MOT #21	2022-04-04 09:34
MOT test number	493532981899
Result	✓ Passed
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #2	20	2022-04-02 11:11
MOT te	st number	652581741966
Result		X Failed
Fail	Nearside Front Road wheel more than one fixing missing (5.2.1 (a) (ii))	
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover missing (5.3.4 (b) (ii))	
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	
Advic	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Fail	Offside Front Anti-roll bar linkage ball joint dust cover missing (5.3.4 (b) (ii))	

page 4/16 CarCheck.co.uk



report date: 2024-03-28

MOT test number

837996258847

Result

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #182021-03-02 11:45MOT test number611531650439Result✓ PassedMOT #172021-03-02 11:45MOT test number131570094338ResultX FailedPass with rectificationEngine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #16

MOT test number

482124637443

Result

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

MOT test number

988335053918

Result

✓ Passed

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number

Result

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))


MOT #13 2017-12-02 10:34 **MOT** test number 116272353255 Result ✓ Passed Nearside Headlamp deteriorated but light output not reduced (1.7.5a) **Advice Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d) Offside Rear TYRE WORN INNER EDGE Advice Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a) Advice Child Seat fitted not allowing full inspection of adult belt

MOT #12		2016-06-25 10:13
MOT test	number	459826788908
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit inner edges (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit inner edges (4.1.E.1)	

CarCheck.co.uk page 6/16



report date: 2024-03-28



MOT #10	2015-06-05 15:44
MOT test number	745756355159
Result	✓ Passed
MOT #9	2015-06-03 10:00
MOT test number	499644655114
Result	X Failed
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Fail Offside Headlamp aim too low (1.8)	
Fail Front brake application uneven (3.7.B.2)	
Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #8		2014-04-15 13:04
MOT test	number	226685404449
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	OFFSIDE REAR TYRE HAS CUTS IN TREAD	

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #7	2014-04-14 10:22	
MOT test number	156244004125	
Result	× Failed	
Notice Nail in nearside front tyre		
Fail Nearside Front Side repeater not working (1.4.A.2c)		
Notice Child seat fitted not allowing full inspection of adult belt		
Notice OFFSIDE REAR TYRE HAS CUTS IN TREAD		
Fail Registration plate lamp not working (1.1.C.1d)		
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough (4.1.D.1a)	to reach the ply or cords	

MOT #6	2013-03-21 11:49
MOT test number	806010283064
Result	✓ Passed
MOT #5	2012-03-21 09:17
MOT test number	879601082089
Result	✓ Passed
MOT #4	2011-02-28 09:14
MOT test number	995359551001
Result	✓ Passed
MOT #3	2010-03-09 16:10
MOT test number	173188060448
Result	✓ Passed
MOT #2	2009-03-10 11:14
MOT test number	630199069027
Result	✓ Passed

CarCheck.co.uk page 8/16



MOT #1 2008-03-06 15:51

MOT test number 520516868049

Result ✓ Passed

CarCheck.co.uk page 9/16



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16




report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner history

e union matery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	UK NK
Plate since	
	More info >

CarCheck.co.uk page 13/16



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 14/16



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2005-03-21
Last registration	2024-04-03
Complete history	See info



Registration #1	2005-03-21	10 mi
Registration #2	2008-03-06	51.558 mi
Registration #3	2009-03-10	63.422 mi
Registration #4	2010-03-09	74.858 mi
Registration #5	2011-02-28	87.506 mi
Registration #6	2012-03-21	92.868 mi
Registration #7	2013-03-21	99.486 mi
Registration #8	2014-04-14	105.784 mi
Registration #9	2014-04-15	105.826 mi
Registration #10	2015-06-03	116.995 mi
Registration #11	2015-06-05	117.011 mi
Registration #12	2016-06-25	128.248 mi
Registration #13	2016-06-25	128.248 mi
Registration #14	2017-12-02	140.081 mi
Registration #15		9.77 66
Registration #16		11.777 es
Registration #17		9.77 66
Registration #18		0.074
Registration #19		9.77 es
Registration #20		0.074
Registration #21		11.777 es
Registration #22		0.074
Registration #23		11.777 mi
Registration #24		11.771 66
Registration #25		11.777 mi
Registration #26		11.777 es
CarCheck.co.uk		

Registration #27

Registration #28

More info >

mn.n.n



Car features

50225	Air conditionin
60295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1550 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Multi-Point Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pag	ge 16/16

Number of axles 2

Engine number 04376082