



TOYOTA

KE54PUF

report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVT-I XT4
Colour	Black
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2022-11-22
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	50
Total items failed	9

MOT #20	2021-11-23 18:36
----------------	------------------

MOT test number	554559133190
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2022-11-22
-------------------------	------------

Advice	Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))
---------------	---

Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
---------------	---

Minor	Front Headlamp lens slightly defective Both (4.1.1 (b) (i))
--------------	---

Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
---------------	--

**MOT #19**

2021-11-22 19:22

MOT test number

144167706745

Result

✗ Failed

- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Minor** Front Headlamp lens slightly defective Both (4.1.1 (b) (i))

MOT #18

2021-03-18 15:39

MOT test number

277605548927

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #17**

2021-03-18 15:39

MOT test number

196783427580

Result

✗ Failed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #16**

2020-04-01 10:40

MOT test number

981687050149

Result

✓ Passed

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #15**

2019-04-06 11:12

MOT test number

448041167586

Result

✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated

**MOT #14**

2018-04-07 09:24

MOT test number

770161063700

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #13

2018-04-07 09:24

MOT test number

660202759139

Result

✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #12

2017-04-01 11:17

MOT test number

538047822876

Result

✓ Passed

MOT #11

2016-04-02 12:53

MOT test number

523154394158

Result

✓ Passed

Advice O/s/f wiper is splitting.

**MOT #10**

2016-04-02 12:53

MOT test number

545722743036

Result**✗ Failed****Advice** O/s/f wiper is splitting.**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9**

2015-04-08 09:21

MOT test number

347268995092

Result**✓ Passed****Advice** Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brake pads starting to get low**Advice** Power steering fluid level low, but not below minimum (2.3.1)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**Notice** Rear tyres are starting to get low

**MOT #8** 2015-04-08 09:21**MOT test number** 439518795032**Result** ✗ Failed

- Advice** Power steering fluid level low, but not below minimum (2.3.1)
- Notice** Rear brake pads starting to get low
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Advice** Power steering component(s) has slight seepage from a component (2.3.3b)
- Notice** Rear tyres are starting to get low
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Advice** Brake pad(s) wearing thin (3.5.1g)

MOT #7 2014-04-07 11:29**MOT test number** 167417894405**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2013-04-04 09:24**MOT test number** 737514293069**Result** ✓ Passed**MOT #5** 2012-04-07 12:12**MOT test number** 116708092086**Result** ✓ Passed

- Notice** N/s/r tyre low on both edges
- Notice** Front tyres low on edges

**MOT #4** 2011-04-07 11:05**MOT test number** 379087491024**Result** ✓ Passed**MOT #3** 2010-04-12 14:38**MOT test number** 190832700181**Result** ✓ Passed**MOT #2** 2009-05-30 08:59**MOT test number** 213560459144**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2008-06-18 18:19**MOT test number** 693320378164**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
6 October 2021

✕
MOT

Expired:
22 November 2022

Tax status	Expired at 6 October 2021
Days left	936 days too late
MOT expiry date	22 November 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	KE54PUF
Plate since	2019-09-28
Current registration	KE54PUF
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-01-31
Last registration	2021-11-23
Complete history	See info



Registration #1	2005-01-31	29 mi
Registration #2	2008-06-18	37.012 mi
Registration #3	2009-05-30	45.927 mi
Registration #4	2010-04-12	52.500 mi
Registration #5	2011-04-07	57.776 mi
Registration #6	2012-04-07	65.428 mi
Registration #7	2013-04-04	73.958 mi
Registration #8	2014-04-07	81.763 mi
Registration #9	2015-04-08	87.904 mi
Registration #10	2016-04-02	94.337 mi
Registration #11	2016-04-02	94.337 mi
Registration #12	2016-04-02	94.337 mi
Registration #13	2016-04-02	94.337 mi
Registration #14	2016-04-02	94.337 mi
Registration #15	2016-04-02	94.337 mi
Registration #16	2016-04-02	94.337 mi
Registration #17	2016-04-02	94.337 mi
Registration #18	2016-04-02	94.337 mi
Registration #19	2016-04-02	94.337 mi
Registration #20	2016-04-02	94.337 mi
Registration #21	2016-04-02	94.337 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1AZ1653805