





report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Blue
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.400 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2022-06-29

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



GV06HNC report date: 2024-03-28

MOT history

MOT expiry date	2024-07-04
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	7
Total items failed	5

MOT #18	2023-06-26 10:57
MOT test number	994396479097
Result	✓ Passed
Next expiry date	2024-07-04

MOT #17	2022-07-05 10:49
MOT test number	421644259746
Result	✓ Passed

MOT #16	2022-06-21 13:15
MOT test number	172115259722
Result	× Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #15		2021-08-23 09:45
MOT test	number	678719044426
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or	cords (5.2.3 (d) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))

MOT #14	2020-05-23 12:41
MOT test number	982400083354
Result	✓ Passed
MOT #13	2019-05-29 11:43
MOT test number	530745149361
Result	✓ Passed
MOT #12	2018-05-11 12:06
MOT test number	136267371367
Result	✓ Passed
MOT #11	2017-05-19 15:22
MOT test number	586378630440
Result	✓ Passed
MOT #10	2017-05-19 15:22
MOT test number	253796169620

MOT test number

Result

Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 4/13



report date: 2024-03-28

× Failed

MOT #9 2016-05-20 09:13

MOT test number 851800383534

MOT #8 2015-05-19 16:21

MOT test number 439299835116

Result ✓ Passed

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #7 2014-05-16 10:59

MOT test number 146536234183

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #6 2013-05-15 15:07

MOT test number 549325133117

Result \(\sqrt{Passed}\)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #5 2012-05-08 12:46

MOT test number 255689922411

Result ✓ Passed

MOT #4 2012-05-08 12:46

MOT test number 345169622141

Result

Pass with rectification Upper Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/13



GV06HNC report date: 2024-03-28

MOT #3	2011-05-06 08:51
MOT test number	675336021124
Result	✓ Passed
MOT #2	2010-04-29 11:55
MOT test number	722249010115
Result	✓ Passed
MOT #1	2009-04-27 10:51
MOT test number	212387719471
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

Plate changes	More info >
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	IIK Sils
Plate since	
	More info >

CarCheck.co.uk page 10/13



GV06HNC report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-04-27
Last registration	2023-06-26
Complete history	See info



Registration #1	2006-04-27	29 mi
Registration #2	2009-04-27	9.773 mi
Registration #3	2010-04-29	13.625 mi
Registration #4	2011-05-06	16.672 mi
Registration #5	2012-05-08	20.448 mi
Registration #6	2013-05-15	23.657 mi
Registration #7	2014-05-16	26.494 mi
Registration #8	2015-05-19	29.305 mi
Registration #9	2016-05-20	31.465 mi
Registration #10	2017-05-19	33.490 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		D.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 4ZZU798028