



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Silver
Year of manufacture	2000
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-18
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-12-16
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	16
Total items failed	27

MOT #22	2021-12-10 16:28
MOT test number	125792565781
Result	✓ Passed
Next expiry date	2022-12-16

MOT #21	2020-11-30 10:45
MOT test number	595776346307
Result	✓ Passed

MOT #20	2020-11-30 10:45
MOT test number	554460732321
Result	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
<b>Pass with rectification</b>	Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

MOT #19	2019-12-17 14:00
MOT test number	697439111230
Result	✓ Passed
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
<b>Advice</b>	Front and rear brake discs slightly corroded
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

**MOT #18** 2019-12-16 14:59**MOT test number** 373609893242**Result** ✗ Failed**Fail** Windscreen washer not working (3.5 (a))**Advice** Front and rear brake discs slightly corroded**Advice** Nearside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**MOT #17** 2018-05-09 11:59**MOT test number** 902121334379**Result** ✓ Passed**MOT #16** 2017-05-17 15:32**MOT test number** 530761382210**Result** ✓ Passed**MOT #15** 2017-04-21 11:05**MOT test number** 435197197545**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)



MOT #14	2016-03-16 13:31
MOT test number	536413966348
Result	✓ Passed

MOT #13	2016-03-07 14:59
MOT test number	230751222208
Result	✗ Failed

- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 205/50/16 (4.1.E.1)
- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Fail** Nearside Rear rear parking brake recording little or no effort not working (3.7.B.6a)



MOT #12 2015-03-21 09:54

MOT test number 619980985016

Result ✓ Passed

**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**Notice** Nearside rear brake disc corroded

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Offside rear tyre slightly out of shape

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2014-03-20 09:27

MOT test number 697209274053

Result ✓ Passed

MOT #10 2013-03-22 09:30

MOT test number 779161883095

Result ✓ Passed

MOT #9 2013-03-22 09:30

MOT test number 546271383052

Result ✗ Failed

**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2012-04-06 14:38**MOT test number** 515447192051**Result** ✓ Passed**MOT #7** 2012-04-06 14:38**MOT test number** 369517392090**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2011-05-09 16:03**MOT test number** 236219821480**Result** ✓ Passed**MOT #5** 2010-04-12 14:52**MOT test number** 273882200169**Result** ✓ Passed**MOT #4** 2009-03-14 10:05**MOT test number** 293183279099**Result** ✓ Passed**Advice** Nearside front brake juddering slightly (3.7.A.2b)**MOT #3** 2008-03-03 13:42**MOT test number** 432173568072**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2007-03-03 16:17
MOT test number	642212667028
Result	✓ Passed
MOT #1	2006-05-26 10:33
MOT test number	363206946113
Result	✓ Passed





Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>W643PDW</b>
Plate since	2019-03-28
Current registration	<b>W643PDW</b>
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2000-06-06
Last registration	2021-12-10
Complete history	<a href="#">See info</a>



Registration #1	2000-06-06	28 mi
Registration #2	2006-05-26	70.721 mi
Registration #3	2007-03-03	75.915 mi
Registration #4	2008-03-03	82.872 mi
Registration #5	2009-03-14	88.313 mi
Registration #6	2010-04-12	94.557 mi
Registration #7	2011-05-09	98.601 mi
Registration #8	2012-04-06	100.097 mi
Registration #9	2013-03-22	108.178 mi
Registration #10	2014-03-20	115.854 mi
Registration #11	2015-03-21	120.023 mi
Registration #12	2016-03-21	120.023 mi
Registration #13	2017-03-21	120.023 mi
Registration #14	2018-03-21	120.023 mi
Registration #15	2019-03-21	120.023 mi
Registration #16	2020-03-21	120.023 mi
Registration #17	2021-03-21	120.023 mi
Registration #18	2022-03-21	120.023 mi
Registration #19	2023-03-21	120.023 mi
Registration #20	2024-03-21	120.023 mi
Registration #21	2025-03-21	120.023 mi
Registration #22	2026-03-21	120.023 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ0571529