



Mercedes-Benz



KW56PZA


report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Blue
Year of manufacture	2007
Top speed	144 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-02
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-26
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	18
Total items failed	7

MOT #16	2023-06-27 16:39
MOT test number	383235620642
Result	✓ Passed
Next expiry date	2024-06-26

MOT #15	2023-06-27 16:39
MOT test number	154337789148
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14**

2022-03-28 08:40

MOT test number

835549076803

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2021-02-01 11:20

MOT test number

109288651169

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front tyre stepped on outer edge

MOT #12

2020-02-19 16:22

MOT test number

426486591649

Result

✓ Passed

- Advice** Rear Brake hose slightly deteriorated Both (1.1.12 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2020-02-17 11:41

MOT test number

317582940425

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake hose slightly deteriorated Both (1.1.12 (b) (ii))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn Rear one of two (5.3.4 (a) (i))

**MOT #10** 2019-01-25 10:39**MOT test number** 675658064779**Result** ✓ Passed**MOT #9** 2018-02-09 12:17**MOT test number** 180102619891**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit Both (4.1.E.1)**MOT #8** 2017-02-02 13:45**MOT test number** 271294179701**Result** ✓ Passed**MOT #7** 2016-02-11 15:39**MOT test number** 931182568111**Result** ✓ Passed**MOT #6** 2015-02-10 12:37**MOT test number** 168181845095**Result** ✓ Passed**Notice** Both front tyres low and cracking**MOT #5** 2014-02-14 10:23**MOT test number** 927295444077**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of near side rear adult belt

**MOT #4** 2013-02-19 15:04**MOT test number** 987670753091**Result** ✓ Passed**Notice** Oil leak from gearbox**MOT #3** 2012-02-15 15:01**MOT test number** 115836242033**Result** ✓ Passed**Notice** Front brake discs worn**Notice** Oil leaking from gearbox ?**MOT #2** 2011-02-16 10:47**MOT test number** 346367341083**Result** ✓ Passed**MOT #1** 2010-01-26 11:56**MOT test number** 643906120067**Result** ✓ Passed**Notice** Oil leak from gearbox



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
26 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	26 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KW56PZA
Plate since	2019-06-29
Current registration	 KW56PZA
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-01-25
Last registration	2023-06-27
Complete history	See info



Registration #1	2007-01-25	12 mi
Registration #2	2010-01-26	16.144 mi
Registration #3	2011-02-16	21.116 mi
Registration #4	2012-02-15	25.764 mi
Registration #5	2013-02-19	30.771 mi
Registration #6	2014-02-14	35.647 mi
Registration #7	2015-02-10	37.367 mi
Registration #8	2016-02-11	42.412 mi
Registration #9	2017-02-02	46.578 mi
Registration #10	2018-02-02	50.777 mi
Registration #11	2019-02-02	55.017 mi
Registration #12	2020-02-02	59.297 mi
Registration #13	2021-02-02	63.617 mi
Registration #14	2022-02-02	67.977 mi
Registration #15	2023-02-02	72.377 mi
Registration #16	2024-02-02	76.817 mi
Registration #17	2025-02-02	81.297 mi
Registration #18	2026-02-02	85.817 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530868737