



BJ59VHV


report date: 2024-03-28

General information

Make	FIAT
Model	500 C POP
Colour	White
Year of manufacture	2009
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-06
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	14
Total items failed	14

MOT #18 2023-06-10 10:02**MOT test number** 983950840411**Result** ✓ Passed**Next expiry date** 2024-07-06**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #17** 2022-06-22 15:42**MOT test number** 142403910303**Result** ✓ Passed**Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MOT #16** 2022-06-22 09:01**MOT test number** 865379212731**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases flexible section broken (6.1.2 (a))**Advice** Front Exhaust mounting defective pipe supporting bracket missing (6.1.2 (a))**Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

**MOT #15** 2021-07-05 16:09**MOT test number** 966290581743**Result** ✓ Passed**MOT #14** 2021-07-05 09:04**MOT test number** 908252370833**Result** ✗ Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Front Macpherson strut likely to become detached top mount corroded through (5.3.3 (a) (ii))

MOT #13 2020-07-07 10:40**MOT test number** 630154174388**Result** ✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #12 2020-07-01 13:02**MOT test number** 259786090781**Result** ✗ Failed

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))



MOT #11	2019-01-04 09:43
MOT test number	326678712882
Result	✓ Passed
Advice	Covers fitted

MOT #10	2019-01-04 09:43
MOT test number	115237811164
Result	✗ Failed
Pass with rectification	Offside Rear Position lamp not working (4.2.1 (a))
Advice	Covers fitted
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9	2018-01-03 10:36
MOT test number	113530447710
Result	✓ Passed
Advice	Nearside Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #8	2018-01-02 14:30
MOT test number	480880217848
Result	✗ Failed
Fail	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)
Advice	Nearside Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #7	2017-01-04 08:41
MOT test number	594836408913
Result	✓ Passed

**MOT #6** 2017-01-03 11:48**MOT test number** 173558985490**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #5** 2016-01-26 10:28**MOT test number** 423086021532**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #4** 2015-01-05 16:13**MOT test number** 479355705090**Result** ✓ Passed**MOT #3** 2015-01-05 16:13**MOT test number** 919445005092**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2013-09-04 10:19**MOT test number** 905517243264**Result** ✓ Passed**MOT #1** 2012-10-10 12:15**MOT test number** 675524782228**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-30
Last registration	2023-06-10
Complete history	See info



Registration #1	2009-10-30	21 mi
Registration #2	2012-10-10	4.684 mi
Registration #3	2013-09-04	7.352 mi
Registration #4	2015-01-05	16.581 mi
Registration #5	2016-01-26	27.008 mi
Registration #6	2017-01-03	34.925 mi
Registration #7	2017-01-04	34.925 mi
Registration #8	2018-01-02	45.757 mi
Registration #9	2018-01-03	45.757 mi
Registration #10	2019-01-04	54.520 mi
Registration #11	2019-01-04	54.520 mi
Registration #12	2019-01-04	54.520 mi
Registration #13	2019-01-04	54.520 mi
Registration #14	2019-01-04	54.520 mi
Registration #15	2019-01-04	54.520 mi
Registration #16	2019-01-04	54.520 mi
Registration #17	2019-01-04	54.520 mi
Registration #18	2019-01-04	54.520 mi
Registration #19	2019-01-04	54.520 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5331536