



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	175 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-05-21
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	24
Total items failed	8

MOT #22	2023-10-17 15:48
MOT test number	669889912343
Result	✓ Passed
Next expiry date	2024-11-13
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #21	2023-10-17 08:45
MOT test number	671603083893
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Headlamp light intensity severely reduced (4.1.4 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #20** 2022-10-21 08:47**MOT test number** 694996575732**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2021-11-03 10:30**MOT test number** 302966076962**Result** ✓ Passed**MOT #18** 2020-11-09 11:18**MOT test number** 413390263124**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge ON LEGAL LIMIT INSIDE EDGE AND NAIL. REPLACE ASAP. 215/50 17 (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened X2 (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened X2 (1.1.14 (a) (ii))**MOT #17** 2019-11-14 13:31**MOT test number** 951379920045**Result** ✓ Passed**Advice** Front Items removed from driver's view prior to test swept area of screen cleared**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge low tread and tyre has a screw in it (5.2.3 (e))

**MOT #16**

2019-11-14 07:45

MOT test number

182215775156

Result**✗ Failed**

MAJOR Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Front Items removed from driver's view prior to test swept area of screen cleared

MAJOR Front Exhaust has a major leak of exhaust gases exhaust flexi joint both layers come apart, emissions test may not be accurate (6.1.2 (a))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge low tread and tyre has a screw in it (5.2.3 (e))

MAJOR Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15

2018-11-07 14:47

MOT test number

766346172307

Result**✓ Passed**

Advice Front Tyre worn close to legal limit/worn on edge x2 (5.2.3 (e))

Minor Front Anti-roll bar linkage ball joint dust cover severely deteriorated x2 (5.3.4 (b) (i))

MOT #14

2018-11-07 12:53

MOT test number

941169976020

Result**✗ Failed**

MAJOR Rear Shock absorbers has a serious fluid leak x2 (5.3.2 (b))

Advice Front Tyre worn close to legal limit/worn on edge x2 (5.2.3 (e))

Minor Front Anti-roll bar linkage ball joint dust cover severely deteriorated x2 (5.3.4 (b) (i))

MOT #13

2017-11-01 11:05

MOT test number

115115548795

Result**✓ Passed**

**MOT #12** 2017-11-01 11:05**MOT test number** 580071776179**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2016-11-03 10:06**MOT test number** 228207334845**Result** ✓ Passed**MOT #10** 2016-11-03 10:06**MOT test number** 391362818616**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #9** 2015-11-04 15:42**MOT test number** 269588645483**Result** ✓ Passed**MOT #8** 2015-11-04 12:13**MOT test number** 430334448003**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7** 2014-11-05 10:06**MOT test number** 836279204375**Result** ✓ Passed**MOT #6** 2013-11-05 10:44**MOT test number** 666969703312**Result** ✓ Passed

**MOT #5** 2012-11-07 12:45**MOT test number** 498152012484**Result** ✓ Passed**MOT #4** 2012-11-07 12:45**MOT test number** 248252612374**Result** ✗ Failed

- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Steering column movement between the shaft and steering wheel (2.1.2b)
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Rear registration plate deteriorated (6.3.1d)

MOT #3 2011-10-26 10:43**MOT test number** 348639691412**Result** ✓ Passed**MOT #2** 2011-10-26 10:43**MOT test number** 368739191410**Result** ✗ Failed

- Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

MOT #1 2010-11-02 11:37**MOT test number** 482966900499**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 OV57RBZ
Plate since	2015-01-01
Current registration	 OV57RBZ
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-12
Last registration	2023-10-17
Complete history	See info



Registration #1	2007-11-12	16 mi
Registration #2	2010-11-02	24.369 mi
Registration #3	2011-10-26	30.604 mi
Registration #4	2012-11-07	37.430 mi
Registration #5	2013-11-05	44.199 mi
Registration #6	2014-11-05	49.702 mi
Registration #7	2015-11-04	53.717 mi
Registration #8	2015-11-04	53.717 mi
Registration #9	2016-11-03	57.749 mi
Registration #10	2016-11-03	57.749 mi
Registration #11	2017-11-01	60.258 mi
Registration #12	2018-10-29	62.277 mi
Registration #13	2019-10-29	64.297 mi
Registration #14	2020-10-29	66.317 mi
Registration #15	2021-10-29	68.337 mi
Registration #16	2022-10-29	70.357 mi
Registration #17	2023-10-17	72.377 mi
Registration #18	2023-10-17	72.377 mi
Registration #19	2023-10-17	72.377 mi
Registration #20	2023-10-17	72.377 mi
Registration #21	2023-10-17	72.377 mi
Registration #22	2023-10-17	72.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1335 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20KX2027