



report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H F SPORT
Colour	White
Year of manufacture	2017
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	181 BHP
Max. torque	221 Nm at 5.400 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B







Internet history

Entry 2



Date	2021-09-19
Pictures	29
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-09-17
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-15
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #5 2023-09-11 14:12

MOT test number 157261988140

Result ✓ Passed

Next expiry date 2024-09-15

- Advice** Nearside Front Tyre wearing on ed
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))
- Advice** TPMS light on due to o/s/r tyre pressure low
- Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))

MOT #4 2023-09-11 08:33

MOT test number 101986017102

Result ✗ Failed

- Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))
- Advice** TPMS light on due to o/s/r tyre pressure low
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre wearing on ed
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))

**MOT #3** 2022-09-09 14:10**MOT test number** 499595394366**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tyre wearing bald on inner edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tyre starting to wear on inner edge (5.2.3 (e))**MOT #2** 2021-09-16 21:10**MOT test number** 239361490072**Result** ✓ Passed**MOT #1** 2020-11-19 13:42**MOT test number** 338006274832**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	F
First licence fee (12 months)	£ 175,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	WG67HNO
Plate since	2019-09-28
Current registration	WG67HNO
Plate since	2019-09-28

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-24
Last registration	2023-09-11
Complete history	See info



Registration #1	2017-11-24	20 mi
Registration #2	2020-11-19	56.858 mi
Registration #3	2021-09-16	65.963 mi
Registration #4	2022-09-20	75.277 mi
Registration #5	2023-09-11	85.277 mi
Registration #6	2023-09-20	95.277 mi
Registration #7	2023-09-20	105.277 mi
Registration #8	2023-09-20	115.277 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1430 mm
Length	4680 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number

2AR1798810