



report date: 2024-03-29

General information

Make	FIAT
Model	500 C C LOUNGE DUALOGIC
Colour	Black
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	61.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-11-09
Pictures	42
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-25
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	23
Total items failed	2

MOT #14	2023-07-26 08:43
MOT test number	494733975249
Result	✓ Passed
Next expiry date	2024-07-25

MOT #13	2023-07-20 11:17
MOT test number	184994287558
Result	✗ Failed
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))
DANGEROUS	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure AND MISSHAPED (5.2.3 (d) (ii))
MAJOR	Front Exhaust has a major leak of exhaust gases needs all from flex back (6.1.2 (a))

MOT #12	2022-07-18 10:51
MOT test number	480439838555
Result	✓ Passed

**MOT #11** 2021-06-25 10:02**MOT test number** 578805548978**Result** ✓ Passed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front tyres both wearing inner edge**Advice** Front Coil spring corroded both (5.3.1 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front strut top slight movement**MOT #10** 2020-07-21 09:25**MOT test number** 765377911439**Result** ✓ Passed**MOT #9** 2020-07-16 11:32**MOT test number** 127552336015**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2019-05-02 09:55**MOT test number** 896948867586**Result** ✓ Passed**MOT #7** 2018-05-03 15:34**MOT test number** 967543066381**Result** ✓ Passed



<b>MOT #6</b>	2017-06-12 12:30
<b>MOT test number</b>	208434767632
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #5</b>	2016-05-19 08:51
<b>MOT test number</b>	915451506592
<b>Result</b>	✓ Passed
<b>Advice</b>	Slight oil leak
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Both front tyres wear edges surface cracking between tread no cords/ply exposed at time
<b>Advice</b>	Front Inner Brake pad(s) wearing thin (3.5.1g)

<b>MOT #4</b>	2016-05-19 08:51
<b>MOT test number</b>	528807605207
<b>Result</b>	✗ Failed
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Both front tyres wear edges surface cracking between tread no cords/ply exposed at time
<b>Pass with rectification</b>	Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)
<b>Advice</b>	Front Inner Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Slight oil leak

<b>MOT #3</b>	2015-05-19 15:28
<b>MOT test number</b>	507969935180
<b>Result</b>	✓ Passed
<b>Notice</b>	Under-trays fitted obscuring some underside components
<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay



MOT #2	2014-06-03 16:50
MOT test number	877924254123
Result	✓ Passed

MOT #1	2014-06-03 15:38
MOT test number	507524554182
Result	✗ Failed

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
25 July 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	25 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>CX11FWW</b>
Plate since	2019-03-29
Current registration	<b>CX11FWW</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-31
Last registration	2023-07-26
Complete history	<a href="#">See info</a>



Registration #1	2011-05-31	26 mi
Registration #2	2014-06-03	35.855 mi
Registration #3	2014-06-03	35.855 mi
Registration #4	2015-05-19	39.566 mi
Registration #5	2016-05-19	42.001 mi
Registration #6	2016-05-19	42.001 mi
Registration #7	2017-06-12	45.350 mi
Registration #8	2018-05-03	50.396 mi
Registration #9	2019-05-20	55.337 mi
Registration #10	2019-05-20	55.337 mi
Registration #11	2019-05-20	55.337 mi
Registration #12	2019-05-20	55.337 mi
Registration #13	2019-05-20	55.337 mi
Registration #14	2019-05-20	55.337 mi
Registration #15	2019-05-20	55.337 mi
Registration #16	2019-05-20	55.337 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1395 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0030351