





### General information

Make	BMW
Model	316 316TI ES
Colour	Green
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	175 Nm at 3.750 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	170 g/km
CO2 label	Н





## Internet history

Entry 1

Date Pictures 2021-06-20

11

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-02-20
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	8
Total items failed	9

MOT #19	2022-02-21 15:02
MOT test number	512921039374
Result	✓ Passed
Next expiry date	2023-02-20

MOT #18	2020-06-23 15:26
MOT test number	845136802188
Result	✓ Passed

MOT #17	2019-07-02 09	9:19
MOT test	<b>number</b> 256984056	6470
Result	V Pas	ssed
Advice	Brake pipe corroded, covered in grease or other material pipes to rear hoses greased (1.1.11 (c	:))





MOT #16	2019-06-19 10:22
MOT test number	198046987202
Result	🗙 Failed
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits	(8.2.1.2 (c))
Advice Nearside Rear Brake pipe corroded, covered in grease or other r	material to the flexi (1.1.11 (c))
Advice Offside Rear fuel cap rubber slightly perished but not leaking	
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds defau	ılt limits (8.2.1.2 (b))
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #15		2018-06-22 15:06
MOT test	number	972343948371
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other materia	al front to rear (1.1.11 (c))

MOT #14	2017-07-31 13:57
MOT test number	446093551739
Result	✓ Passed
<b>Advice</b> Front Brake hose slightly deteriorated both (3.6.B.4d)	

MOT #13	2017-07-24 11:59
MOT test number	772090201338
Result	🗙 Failed
<b>Fail</b> Nearside Rear Front suspension has excessive movement at a wishbone pin or bush rear bush (2.5.A.1c)	n Front wishbone
Advice Front Brake lining(s) wearing thin (3.5.1g)	
<b>Fail</b> Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	
<b>Fail</b> Offside Front Front suspension has excessive movement at a wishbone pin or bush Front wishbone rear bush (2.5.A.1c)	
<b>Fail</b> Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D	0.3)





MOT #12	2016-07-22 11:02
MOT test number	491736098164
Result	✓ Passed
MOT #11	2015-07-27 16:03
MOT test number	225178305243
Result	✓ Passed
MOT #10	2014-07-03 13:57

MOT #10	2014-07-05 15:57
MOT test number	907804384177
Result	✓ Passed
Notice Nail in offside front tyre	

MOT #9	2013-08-27 09:01
MOT test number	556299333290
Result	✓ Passed

MOT #8	2013-08-22 09:32
MOT test number	309634933291
Result	🗙 Failed
<b>Fail</b> Electronic stability system warning lamp indicates a fault (3.4.1c)	

MOT #7	2012-08-03 10:50
MOT test number	675926712230
Result	✓ Passed

MOT #6	2011-08-01 08:35
MOT test number	295983111201
Result	✓ Passed





MOT #5	2010-08-17 15:56
MOT test number	960899320288
Result	✓ Passed
MOT #4	2010-08-04 10:41
MOT test number	582296410258
Result	🗙 Failed
Fail         Nearside Rear coil spring cracked (2.4.C.1a)	
FailOffside Rear coil spring cracked (2.4.C.1a)	
MOT #3	2009-08-28 09:11
MOT test number	310690949463
Result	Passed
MOT #2	2008-12-22 17:09
MOT #2 MOT test number	2008-12-22 17:09 231907058311
MOT test number	231907058311
MOT test number	231907058311
MOT test number Result	231907058311 <pre> </pre> Passed



Tax & MOT check

X Untaxed Tax expired: 8 June 2021	<b>X</b> <b>MOT</b> Expired: 20 February 2023
Tax status	Expired at 8 June 2021
Days left	1056 days too late
MOT expiry date	20 February 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	AF I
Category	ante.
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plates	i.
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-09-01
Last registration	2022-02-21
Complete history	See info



Registration #1	2004-09-01	17 mi
Registration #2	2007-10-13	36.814 mi
Registration #3	2008-12-22	40.619 mi
Registration #4	2009-08-28	46.418 mi
Registration #5	2010-08-04	49.529 mi
Registration #6	2010-08-17	49.737 mi
Registration #7	2011-08-01	52.564 mi
Registration #8	2012-08-03	55.745 mi
Registration #9	2013-08-22	59.262 mi
Registration #10	2013-08-27	59.262 mi
Registration #11	2014-07-03	60.937 mi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.707 esi
Registration #16		11.777 est
Registration #17		11.707 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.317 est
Registration #21		10.319 est

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight		
Width	1751 mm	
Height	1408 mm	
Length	4262 mm	
Wheel base	2700 mm	
Kerb weight	1375 kg	
Additional information		
Fuel tank capacity	63 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of axles	2	
Engine number CarCheck.co.uk	A086H177 page 13	3/13