



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SE LUX D S40
Colour	Red
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	7
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	15
Total items failed	9

MOT #20	2023-10-09 12:36
MOT test number	901083798410
Result	✓ Passed
Next expiry date	2024-10-26

MOT #19	2023-10-09 08:09
MOT test number	888446704739
Result	✗ Failed
Fail	Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18	2022-10-14 07:36
MOT test number	464075786931
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2021-10-27 14:46
MOT test number	854952877016
Result	✓ Passed

**MOT #16** 2021-04-26 11:40**MOT test number** 809049766281**Result** ✓ Passed**MOT #15** 2019-12-06 11:05**MOT test number** 925565956495**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.04mm (5.2.3 (e))**MOT #14** 2018-11-27 11:28**MOT test number** 297251950097**Result** ✓ Passed**MOT #13** 2018-11-26 11:19**MOT test number** 601000105494**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #12** 2017-11-20 16:46**MOT test number** 861448131813**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2017-11-20 16:46**MOT test number** 673253396336**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Nearside Steering rack gaiter insecure (2.2.D.2d)**MOT #10** 2016-12-15 12:17**MOT test number** 257968145731**Result** ✓ Passed**MOT #9** 2016-06-23 14:09**MOT test number** 117802100640**Result** ✓ Passed**MOT #8** 2015-06-23 11:34**MOT test number** 585784075162**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-06-27 12:51**MOT test number** 128258074168**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2014-06-27 09:47**MOT test number** 237908874484**Result** ✗ Failed**Fail** Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2013-07-01 16:52**MOT test number** 666192083151**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-07-01 16:52**MOT test number** 338382483136**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-06-29 12:16**MOT test number** 728321382150**Result** ✓ Passed**MOT #2** 2012-06-29 11:55**MOT test number** 175441982142**Result** ✗ Failed**Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)



MOT #1	2011-05-16 10:18
MOT test number	525526931187
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-22
Last registration	2023-10-09
Complete history	See info



Registration #1	2008-05-22	13 mi
Registration #2	2011-05-16	10.593 mi
Registration #3	2012-06-29	14.026 mi
Registration #4	2012-06-29	14.026 mi
Registration #5	2013-07-01	14.172 mi
Registration #6	2014-06-27	26.147 mi
Registration #7	2014-06-27	26.147 mi
Registration #8	2015-06-23	30.901 mi
Registration #9	2016-06-23	35.897 mi
Registration #10	2016-12-15	37.970 mi
Registration #11	2017-11-20	46.755 mi
Registration #12	2018-05-22	51.277 mi
Registration #13	2018-05-22	51.277 mi
Registration #14	2018-05-22	51.277 mi
Registration #15	2018-05-22	51.277 mi
Registration #16	2018-05-22	51.277 mi
Registration #17	2018-05-22	51.277 mi
Registration #18	2018-05-22	51.277 mi
Registration #19	2018-05-22	51.277 mi
Registration #20	2018-05-22	51.277 mi
Registration #21	2018-05-22	51.277 mi
Registration #22	2018-05-22	51.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	411629