





report date: 2024-03-28

General information

Make	FORD
Model	RANGER XL 4X4 DCB TDCI
Colour	Red
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	31.4 mpg
Consumption combined	27.2 mpg



CarCheck.co.uk page 1/13



Internet history

Entry 1

 Date
 2021-01-31

 Pictures
 1

Listing price <u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	13
Total items failed	9

MOT #14		2024-04-25 09:48
MOT test	number	168210914473
Result		✓ Passed
Next expi	ry date	2025-04-24
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.1)	1 (c))
Advice	Vehicle has corrosion underneath	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.	.11 (c))

MOT #13	2024-04-23 09:22
MOT test number	194769563716
Result	× Failed
Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, ingress of dirt (6.1.7 (g) (ii))	no longer prevents the
Advice Nearside Front Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
Advice Vehicle has corrosion underneath	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1	1.11 (c))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2023-11-14 13:05

MOT test number 937053794357

Result \rightarrow Passed

Advice Vehicle has corrosion underneath

Advice Vehicle has been wax oiled underneath

MOT #11 2021-12-23 12:21

MOT test number 564038835477

Result ✓ Passed

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2021-12-23 10:48

MOT test number 716882873554

Result X Failed

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))

MOT #9 2021-05-14 14:57

MOT test number 790157522099

Result ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

мот #	8	2021-05-13 09:05
MOT to	est number	450083720850
Result		X Failed
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of	its structure (5.2.3 (d) (ii))
Fail	Nearside Rear Registration plate lamp inoperative in the case of a single	lamp or all lamps (4.7.1 (b)
Fail (ii))	Offside Rear Registration plate lamp inoperative in the case of a single la	mp or all lamps (4.7.1 (b)
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MOT #	7	2019-05-28 14:53

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MOT #7	2019-05-28 14:53
MOT test number	984886243770
Result	✓ Passed
MOT #6	2018-05-29 14:43
MOT test number	958694883666
Result	✓ Passed
MOT #5	2017-04-11 14:35
MOT test number	353072822819
Result	✓ Passed
MOT #4	2016-02-23 10:12
MOT test number	723543895796
Result	✓ Passed

MOT #3	2015-02-09 11:37
MOT test number	239520745025
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2	2014-02-24 15:17
MOT test number	518475254074
Result	✓ Passed
MOT #1	2013-02-27 10:23
MOT test number	835628953049
Result	✓ Passed

CarCheck.co.uk page 6/13




24 April 2025

See MOT history

Tax & MOT check

MOT expiry date

Full MOT history



CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e inter initiation	
For how long did the current and previous owner(s) have this FORD? How many owners defined the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
THE PARTY OF THE P	

	More info >
Plate changes	·
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
	III IIIIICS
Mileage registrations	16
First mileage registration	2010-03-02
Last registration	2024-04-25
Complete history	See info



Registration #1	2010-03-02	9 mi
Registration #2	2013-02-27	26.291 mi
Registration #3	2014-02-24	33.717 mi
Registration #4	2015-02-09	40.831 mi
Registration #5	2016-02-23	48.924 mi
Registration #6	2017-04-11	59.317 mi
Registration #7	2018-05-29	71.505 mi
Registration #8	2019-05-28	82.320 mi
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.177 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	*****
Video	see crash video



Dimensions & weight

Width	1788 mm
Height	805 mm
Length	5080 mm
Kerb weight	1845 kg
Max. allowed weight	2985 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number Carcheck.co.uk	1201936 page 13/13