





report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



YR59ZZW report date: 2024-03-29

Internet history

Εı	n	tı	'V	,	1

Life y 1	
Date	2021-08-02
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-08-20
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	7

MOT #16		2023-08-19 10:57
MOT test	number	181289486412
Result		✓ Passed
Next exp	iry date	2024-08-20
Advice	Rear Subframe mounting prescribed area is corroded but not considered ex	ccessive (5.3.6 (a) (i))
Advice	Front Subframe mounting prescribed area is corroded but not considered ex	xcessive (5.3.6 (a) (i))
Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))		

MOT #15		2022-08-18 15:36
MOT test i	number	467881760445
Result		✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))	
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #14 2022-08-18 14:13 524500366151 **MOT** test number Result × Failed Fail Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d)) Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii)) Advice **Advice** Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))

MOT #13	2021-08-21 12:52
MOT test number	755670611879
Result	✓ Passed
MOT #12	2020-11-09 17:00
MOT test number	855447156953
Result	✓ Passed

MOT #11	2020-11-09 09:40
MOT test number	368281682590
Result	× Failed
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10 2019-11-11 14:24

MOT test number 451463136041

Result ✓ Passed

MOT #9 2018-10-29 13:56

MOT test number 922679130139

Result

Passed

MOT #8 2017-11-13 16:21

MOT test number 222217621737

Result \(\sqrt{Passed} \)

MOT #7 2017-11-13 11:56

MOT test number 652714708226

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (4.1.D.1a)

Advice Iten

Items removed from driver's view prior to test

MOT #6 2016-11-14 11:27

MOT test number 121044359672

Result \rightarrow Passed

MOT #5 2015-10-30 13:37

MOT test number 667078442345

Result ✓ Passed

MOT #4 2015-10-29 13:33

MOT test number 407833731860

Result × Failed

Fail Nearside Front coil spring broken (2.4.C.1a)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3	2014-11-01 10:23
MOT test number	886965304340
Result	✓ Passed
Notice Exhaust back box corroded	

Notice Exhaust back box corroded	
MOT #2	2013-11-09 10:25
MOT test number	919393313375
Result	✓ Passed
MOT #1	2012-10-25 10:27
MOT test number	897979292284
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

,	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIEZ ZIIS UK
Plate since	200-0-0
Current registration	IK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-12
Last registration	2023-08-19
Complete history	See info



Registration #1	2009-11-12	6 mi
Registration #2	2012-10-25	19.228 mi
Registration #3	2013-11-09	24.633 mi
Registration #4	2014-11-01	28.197 mi
Registration #5	2015-10-29	33.392 mi
Registration #6	2015-10-30	33.396 mi
Registration #7	2016-11-14	38.369 mi
Registration #8	2017-11-13	41.961 mi
Registration #9	2017-11-13	41.961 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.177 es
Registration #16		11.777 es
Registration #17		11.777 mi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 9519694