



report date: 2024-03-29

General information

Make	MINI
Model	COOPER S
Colour	Blue
Year of manufacture	2012
Top speed	142 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-31
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	27
Total items failed	4

MOT #12	2023-07-22 10:06
MOT test number	865931922007
Result	✓ Passed
Next expiry date	2024-07-31

MOT #11	2022-08-01 14:44
MOT test number	955733186225
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-07-15 13:11
MOT test number	480367295891
Result	✓ Passed

**MOT #9** 2020-09-24 13:11**MOT test number** 727954258335**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #8** 2020-09-10 12:23**MOT test number** 279087206313**Result** ✗ Failed**Fail** Front Headlamp aim too low both (4.1.2 (a))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #7** 2019-09-20 13:10**MOT test number** 667035972920**Result** ✓ Passed**Advice** Windscreen has slight damage, view of road not affected

**MOT #6** 2018-09-25 11:48**MOT test number** 460076452950**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view view not affected (3.2 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))**MOT #5** 2018-09-25 11:48**MOT test number** 858399827452**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))**Pass with rectification** Nearside Reversing lamp inoperative (4.6.1 (a))**Minor** Windscreen damaged but not adversely affecting driver's view view not affected (3.2 (a) (i))**MOT #4** 2017-09-26 08:21**MOT test number** 184188968641**Result** ✓ Passed**Advice** Nearside Rear tyre inner sidewall small cut, within limit**Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front tyre slight wear outer edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #3**

2017-09-26 08:21

**MOT test number**

243107817838

**Result****✗ Failed****Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front tyre slight wear outer edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear tyre inner sidewall small cut, within limit**MOT #2**

2016-09-02 12:33

**MOT test number**

189963029919

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1**

2015-09-25 15:04

**MOT test number**

587028161479

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
31 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	31 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-27
Last registration	2023-07-22
Complete history	<a href="#">See info</a>



Registration #1	2012-09-27	21 mi
Registration #2	2015-09-25	24.973 mi
Registration #3	2016-09-02	30.271 mi
Registration #4	2017-09-26	43.142 mi
Registration #5	2017-09-26	43.142 mi
Registration #6	2018-09-25	58.510 mi
Registration #7	2018-09-25	58.510 mi
Registration #8	2019-09-25	58.510 mi
Registration #9	2019-09-25	58.510 mi
Registration #10	2019-09-25	58.510 mi
Registration #11	2019-09-25	58.510 mi
Registration #12	2019-09-25	58.510 mi
Registration #13	2019-09-25	58.510 mi
Registration #14	2019-09-25	58.510 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	A631J326