



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Silver
Year of manufacture	2007
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	220 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-17
Pictures	26
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2022-10-08
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	37
Total items failed	5

MOT #12 2021-10-09 11:12**MOT test number** 992778956561**Result** Passed**Next expiry date** 2022-10-08

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Front oil leak
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2020-07-10 12:26**MOT test number** 805718808313**Result** Passed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10** 2019-03-15 16:52**MOT test number** 265386111265**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing side wall damage (5.2.3 (d) (ii))**Advice** Oil leak**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**MOT #9** 2018-03-15 15:09**MOT test number** 520503232257**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-03-15 13:54**MOT test number** 311627183736**Result** ✓ Passed**MOT #7** 2016-03-16 11:37**MOT test number** 121683683637**Result** ✓ Passed**Advice** Advise front tyres scrubbing on inner edge**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2016-03-15 08:28

MOT test number

195091628227

Result**✗ Failed****Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Advise engine oil leak**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Electronic parking brake control defective so that it cannot be satisfactorily operated (3.1.3c)**Advice** Advise front tyres scrubbing on inner edge**MOT #5**

2013-05-03 15:32

MOT test number

517623023173

Result**✓ Passed****Notice** N/s front tyre worn on edges**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Sill covers fitted**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**MOT #4**

2012-05-10 10:10

MOT test number

509761732170

Result**✓ Passed****Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #3** 2011-05-20 13:59**MOT test number** 455110641168**Result** ✓ Passed**Notice** Nearside spot lamp lens damaged.**Notice** Nearside front shock absorber has a noisy lower pivot.**MOT #2** 2011-05-19 16:07**MOT test number** 125559831197**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Nearside front shock absorber has a noisy lower pivot.**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Both front brake discs worn (ribbed).**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Nearside spot lamp lens damaged.**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-03-29 13:19**MOT test number** 641298680026**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 June 2022

✕
MOT

Expired:
8 October 2022

Tax status	Expired at 1 June 2022
Days left	698 days too late
MOT expiry date	8 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-03-27
Last registration	2021-10-09
Complete history	See info



Registration #1	2007-03-27	18 mi
Registration #2	2010-03-29	37.257 mi
Registration #3	2011-05-19	53.942 mi
Registration #4	2011-05-20	53.942 mi
Registration #5	2012-05-10	70.793 mi
Registration #6	2013-05-03	81.590 mi
Registration #7	2016-03-15	86.417 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040339215