



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-09-12
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-15
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	3

MOT #13	2023-09-12 16:48
MOT test number	830460954942
Result	✓ Passed
Next expiry date	2024-09-15
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12	2023-09-12 10:24
MOT test number	483360336444
Result	✗ Failed
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2022-08-30 08:04
MOT test number	241278325378
Result	✓ Passed
Advice	Front oil leak
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10** 2021-09-16 14:07**MOT test number** 842876518498**Result** ✓ Passed**MOT #9** 2021-03-10 12:54**MOT test number** 974098058864**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2020-03-09 12:44**MOT test number** 143321560133**Result** ✓ Passed**Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2020-03-09 12:44**MOT test number** 440317016444**Result** ✗ Failed**Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2019-01-24 12:04**MOT test number** 970742206894**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-01-18 11:21**MOT test number** 598241691409**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin pads (3.5.1g)**MOT #4** 2017-01-30 12:06**MOT test number** 695936551609**Result** ✓ Passed**MOT #3** 2017-01-30 09:05**MOT test number** 976311141876**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #2** 2016-01-14 11:14**MOT test number** 627617340033**Result** ✓ Passed**MOT #1** 2016-01-14 11:14**MOT test number** 229542700849**Result** ✗ Failed**Pass with rectification** Nearside Rear Inner Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 September 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FD62UKR
Plate since	2019-09-29
Current registration	 FD62UKR
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-24
Last registration	2023-09-12
Complete history	See info



Registration #1	2013-01-24	17 mi
Registration #2	2016-01-14	68.243 mi
Registration #3	2016-01-14	68.243 mi
Registration #4	2017-01-30	88.506 mi
Registration #5	2017-01-30	88.506 mi
Registration #6	2018-01-18	107.847 mi
Registration #7	2019-01-24	116.287 mi
Registration #8	2020-03-09	122.504 mi
Registration #9	2020-03-09	122.504 mi
Registration #10	2020-03-09	122.504 mi
Registration #11	2020-03-09	122.504 mi
Registration #12	2020-03-09	122.504 mi
Registration #13	2020-03-09	122.504 mi
Registration #14	2020-03-09	122.504 mi
Registration #15	2020-03-09	122.504 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ