



report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | CITROEN |
| Model | DS5 HYBRID4 DSPORT EGS |
| Colour | White |
| Year of manufacture | 2012 |
| Top speed | 131 mph |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 200 BHP |
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Electric / Diesel |
| Consumption city | 72.4 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 107 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-23 |
| Pictures | 32 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-15 |
| MOT pass rate | 100 % |
| MOT passed | 9 |
| Failed MOT tests | 0 |
| Total advice items | 28 |
| Total items failed | 0 |

MOT #9 2023-11-15 16:42

MOT test number 296105490833

Result ✓ Passed

Next expiry date 2024-11-15

- Advice** Nearside Rear Tyre slightly damaged slight sidewall damage (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Ref emissions test no acceleration detected no print out
- Advice** Offside Front Tyre slightly damaged slight sidewall damage (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm inner (5.2.3 (e))
- Advice** Central Rear Standard fitment seat belt missing
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged slight sidewall damage (5.2.3 (d) (ii))

MOT #8 2022-11-09 13:48

MOT test number 261711941145

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge cracking (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge cracking (5.2.3 (e))

**MOT #7** 2021-11-15 14:04**MOT test number** 314562899135**Result** ✓ Passed**Advice** Nearside Rear tyre 1.6mm**Advice** Nearside Front various cuts to tyre side wall**Advice** Offside Rear tyre 2mm and bald on edge**MOT #6** 2020-10-17 07:49**MOT test number** 175502491589**Result** ✓ Passed**MOT #5** 2019-04-30 09:27**MOT test number** 202734156589**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge tyre wear (5.2.3 (e))**Advice** Advise ref emissions test no acceleration detected no print out**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge tyre wear (5.2.3 (e))**Advice** Advise engine covers fitted**MOT #4** 2018-05-10 09:43**MOT test number** 427967676772**Result** ✓ Passed**Advice** Advise ref emissions test no acceleration detected no print out**Advice** Advise engine covers fitted

**MOT #3** 2017-05-09 11:00**MOT test number** 557630316617**Result** ✓ Passed**Advice** Undercovers fitted**Advice** No smoke detected no printout**MOT #2** 2016-04-26 13:00**MOT test number** 822962179752**Result** ✓ Passed**Advice** No smoke detected no printout**Advice** Engine and undercovers fitted**MOT #1** 2015-05-13 11:18**MOT test number** 237843435427**Result** ✓ Passed**Notice** Advise ref emission test no acceleration de-tected reading k=0.01 1/m**Notice** Under-trays fitted obscuring some underside components**Notice** Advise tyres have outer sidewall damage to kerbin ribs**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
15 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 15 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 59 |
| Band | B |
| Single payment (12 months) | £ 10,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 10,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,000 |
| Auction value | £ 15,000 |
| Average private trade value | £ 15,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2012-05-15 |
| Last registration | 2023-11-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-05-15 | 13 mi |
| Registration #2 | 2015-05-13 | 21.513 mi |
| Registration #3 | 2016-04-26 | 26.819 mi |
| Registration #4 | 2017-05-09 | 31.870 mi |
| Registration #5 | 2018-05-10 | 35.067 mi |
| Registration #6 | 2019-04-30 | 40.255 mi |
| Registration #7 | 2020-05-20 | 45.277 mi |
| Registration #8 | 2021-05-20 | 50.277 mi |
| Registration #9 | 2022-05-20 | 55.277 mi |
| Registration #10 | 2023-05-20 | 60.277 mi |
| Registration #11 | 2023-11-15 | 65.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 83% |
| Pedestrian | 40% |
| Safety systems | 97% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1850 mm |
| Height | 1508 mm |
| Length | 4530 mm |
| Wheel base | 2727 mm |
| Kerb weight | 1740 kg |
| Max. allowed weight | 2265 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DYZC4003835 |