



EK600MZ

report date: 2024-03-28

General information

| | |
|---------------------|-----------------------------------|
| Make | FORD |
| Model | TRANSIT CONNECT T200 TREND LR P/V |
| Colour | Grey |
| Year of manufacture | 2010 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-----------------|---------------------|
| Power | 90 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.753 cc |
| Cylinders | 4 |
| Fuel type | Diesel |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-07 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-15 |
| MOT pass rate | 75 % |
| MOT passed | 12 |
| Failed MOT tests | 4 |
| Total advice items | 28 |
| Total items failed | 13 |

| | |
|------------------|---|
| MOT #16 | 2024-02-27 12:04 |
| MOT test number | 430957697581 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-15 |
| Advice | Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Minor | Central Front Lower Windscreen damaged but not adversely affecting driver's view Stone chip in windscreen (3.2 (a) (i)) |
| Advice | Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) |

| | |
|-----------------|--|
| MOT #15 | 2023-03-10 10:20 |
| MOT test number | 997776196133 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #14**

2022-03-09 15:57

MOT test number

877630053706

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Requires brake fluid change**MOT #13**

2022-03-09 11:38

MOT test number

834816460295

Result

✗ Failed

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Crank sensor loom insecure rubbing driveshaft**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Inner Drive shaft joint excessively worn (6.1.7 (c) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Requires brake fluid change**Advice** Nearside Rear park brake low effort**MOT #12**

2021-03-13 09:38

MOT test number

244975337767

Result

✓ Passed

MOT #11

2020-03-16 16:32

MOT test number

105390648378

Result

✓ Passed

**MOT #10**

2020-03-07 09:43

MOT test number

979888443778

Result**✗ Failed**

- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Fuel hose leaking two pipes to fuel tank (6.1.3 (b) (i))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Wheel bearing rough when rotated and noisy (5.1.3 (b) (i))

MOT #9

2019-03-11 11:04

MOT test number

381062990039

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Fuel filler neck rubber perished.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8** 2019-03-11 09:16**MOT test number** 522124951786**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Fuel filler neck rubber perished.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #7 2018-02-21 16:50**MOT test number** 217478912605**Result** ✓ Passed**MOT #6** 2017-02-23 17:03**MOT test number** 865460014831**Result** ✓ Passed**MOT #5** 2016-03-14 17:14**MOT test number** 845972639896**Result** ✓ Passed**MOT #4** 2015-09-28 13:52**MOT test number** 350737992845**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|------------------|
| MOT #3 | 2014-09-25 15:59 |
| MOT test number | 596258564219 |
| Result | ✓ Passed |

| | |
|-------------------------|---|
| MOT #2 | 2014-09-25 15:59 |
| MOT test number | 507968164259 |
| Result | ✗ Failed |
| Pass with rectification | Centre Stop lamp not working (1.2.1b) |
| Pass with rectification | Nearside Headlamp not working on dipped beam (1.7.5a) |

| | |
|-----------------|------------------|
| MOT #1 | 2013-09-27 11:46 |
| MOT test number | 755230673215 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
15 March 2025

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 April |
| Days left | | 338 |
| MOT expiry date | | 15 March 2025 |
| Full MOT history | | See MOT history |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | EK600MZ |
| Plate since | 2024-03-28 |
| Current registration | EK600MZ |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-09-30 |
| Last registration | 2024-02-27 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-09-30 | 6 mi |
| Registration #2 | 2013-09-27 | 20.817 mi |
| Registration #3 | 2014-09-25 | 29.230 mi |
| Registration #4 | 2015-09-28 | 37.937 mi |
| Registration #5 | 2016-03-14 | 41.590 mi |
| Registration #6 | 2017-02-23 | 47.288 mi |
| Registration #7 | 2018-02-21 | 54.095 mi |
| Registration #8 | 2019-03-11 | 59.268 mi |
| Registration #9 | 2019-03-11 | 59.268 mi |
| Registration #10 | 2019-03-11 | 59.268 mi |
| Registration #11 | 2019-03-11 | 59.268 mi |
| Registration #12 | 2019-03-11 | 59.268 mi |
| Registration #13 | 2019-03-11 | 59.268 mi |
| Registration #14 | 2019-03-11 | 59.268 mi |
| Registration #15 | 2019-03-11 | 59.268 mi |
| Registration #16 | 2019-03-11 | 59.268 mi |
| Registration #17 | 2019-03-11 | 59.268 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1795 mm |
| Height | 1815 mm |
| Length | 4275 mm |
| Wheel base | 2664 mm |
| Kerb weight | 1399 kg |
| Max. allowed weight | 2040 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 9E51888 |