



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX INVINCIBLE D-4D DCP
Colour	Black
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	430 Nm at 1.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-11
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-26
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	34
Total items failed	9

MOT #19 2024-03-27 17:26

MOT test number 670186440185

Result ✓ Passed

Next expiry date 2025-03-26

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Prop shaft joint worn, but not excessively rear prop front joint (6.1.7 (c) (i))

MOT #18 2024-03-27 17:26

MOT test number 606435856823

Result ✗ Failed

- Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Prop shaft joint worn, but not excessively rear prop front joint (6.1.7 (c) (i))

**MOT #17**

2023-03-21 17:47

MOT test number

124363297616

Result

✓ Passed

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #16**

2023-03-21 17:47

MOT test number

219575075942

Result

✗ Failed

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**MOT #15**

2022-03-09 16:20

MOT test number

596258539963

Result

✓ Passed

**MOT #14**

2022-02-28 09:39

MOT test number

593699266254

Result

✗ Failed

- MAJOR** Nearside Rear Fuel tank insecure Tank strap corroded (6.1.3 (a) (i))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- MAJOR** Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner and outer sill (6.1.1 (c) (i))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Passenger seat(s) missing at time of test Bench seat
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner and outer sill (6.1.1 (c) (i))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Nail in tyre
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13

2021-02-12 10:19

MOT test number

751584275471

Result

✓ Passed

- Advice** Both inner sills corroded & becoming weak
- Advice** Offside Rear Outer sill corroded & becoming weak

MOT #12

2020-02-03 15:50

MOT test number

855807779662

Result

✓ Passed

**MOT #11** 2020-02-03 13:46**MOT test number** 877926374863**Result** ✗ Failed**MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))**MOT #10** 2019-02-04 11:53**MOT test number** 628227334179**Result** ✓ Passed**MOT #9** 2018-02-06 18:04**MOT test number** 431825361546**Result** ✓ Passed**MOT #8** 2018-01-31 09:12**MOT test number** 228195469080**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded front to rear (3.6.B.2c)**Fail** Offside Rear Inner Brake pipe excessively corroded front to rear (3.6.B.2c)**MOT #7** 2017-01-24 11:26**MOT test number** 959216230887**Result** ✓ Passed**MOT #6** 2016-01-20 10:00**MOT test number** 884467223884**Result** ✓ Passed**MOT #5** 2015-01-26 09:51**MOT test number** 636416325064**Result** ✓ Passed

**MOT #4** 2014-01-06 13:09**MOT test number** 576296104055**Result** ✓ Passed**MOT #3** 2013-01-24 09:32**MOT test number** 405064023062**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2013-01-24 09:32**MOT test number** 578424323073**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Horn not working (1.6.2a)**MOT #1** 2012-02-01 10:39**MOT test number** 115022832071**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Both rear tyres 3mm of tread approx in centre of treads



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
26 March 2025

Tax status

Valid until 1 September

Days left

126

MOT expiry date

26 March 2025

Full MOT history


[See MOT history](#)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-02-24
Last registration	2024-03-27
Complete history	See info



Registration #1	2009-02-24	28 mi
Registration #2	2012-02-01	34.548 mi
Registration #3	2013-01-24	45.772 mi
Registration #4	2014-01-06	55.791 mi
Registration #5	2015-01-26	68.632 mi
Registration #6	2016-01-20	79.128 mi
Registration #7	2017-01-24	85.578 mi
Registration #8	2018-01-31	94.255 mi
Registration #9	2018-02-06	94.269 mi
Registration #10	2019-02-04	100.838 mi
Registration #11	2019-03-20	101.377 mi
Registration #12	2019-03-20	101.377 mi
Registration #13	2019-03-20	101.377 mi
Registration #14	2019-03-20	101.377 mi
Registration #15	2019-03-20	101.377 mi
Registration #16	2019-03-20	101.377 mi
Registration #17	2019-03-20	101.377 mi
Registration #18	2019-03-20	101.377 mi
Registration #19	2019-03-20	101.377 mi
Registration #20	2019-03-20	101.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1810 mm
Length	5255 mm
Kerb weight	1885 kg
Max. allowed weight	2940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD7547097