



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Blue
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-23
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #17	2023-07-17 12:57
MOT test number	510605023396
Result	✓ Passed
Next expiry date	2024-07-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-07-09 15:56
MOT test number	561972343660
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge heavily worn to the inner edge (5.2.3 (e))

**MOT #15**

2022-07-09 11:26

MOT test number

151057527492

Result**✗ Failed****MAJOR** Offside Headlamp aim not tested (4.1.2 (b))**DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge heavily worn to the inner edge (5.2.3 (e))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge devoid of tread to the inner edge (5.2.3 (e))**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #14**

2021-06-23 10:08

MOT test number

404239167440

Result**✓ Passed****MOT #13**

2020-09-10 16:19

MOT test number

119273005721

Result**✓ Passed****MOT #12**

2019-09-11 09:38

MOT test number

557019597989

Result**✓ Passed****Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Slight oil leak from gearbox**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2018-09-14 15:19**MOT test number** 744889710408**Result** ✓ Passed**MOT #10** 2017-09-11 11:27**MOT test number** 672255584268**Result** ✓ Passed**MOT #9** 2017-09-11 08:52**MOT test number** 440850091498**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #8** 2016-09-21 13:46**MOT test number** 224438123753**Result** ✓ Passed**Advice** Exhaust hanger bracket corroded off second from rear**MOT #7** 2015-09-21 11:56**MOT test number** 392407239810**Result** ✓ Passed**MOT #6** 2015-09-21 11:56**MOT test number** 753312868805**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Offside Rear coil spring broken (2.4.C.1a)



MOT #5	2014-09-29 11:06
MOT test number	117202374232
Result	✓ Passed
<div>NoticeNs + os front tyres have 3mm tread remaining</div>	
MOT #4	2013-09-16 14:42
MOT test number	289639453223
Result	✓ Passed
MOT #3	2012-09-20 12:10
MOT test number	925674562271
Result	✓ Passed
MOT #2	2011-09-19 14:56
MOT test number	498142961226
Result	✓ Passed
MOT #1	2010-09-21 09:30
MOT test number	572644360296
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 December 2023

✓

MOT

Expires:
16 July 2024

Tax status	Expired at 1 December 2023
Days left	149 days too late
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	NG57ANV
Plate since	2019-06-29
Current registration	NG57ANV
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-10
Last registration	2023-07-17
Complete history	See info



Registration #1	2007-10-10	28 mi
Registration #2	2010-09-21	15.558 mi
Registration #3	2011-09-19	18.638 mi
Registration #4	2012-09-20	21.384 mi
Registration #5	2013-09-16	28.559 mi
Registration #6	2014-09-29	34.820 mi
Registration #7	2015-09-21	39.540 mi
Registration #8	2015-09-21	39.540 mi
Registration #9	2016-09-21	44.446 mi
Registration #10	2017-09-11	47.557 mi
Registration #11	2018-09-21	51.557 mi
Registration #12	2019-09-21	55.557 mi
Registration #13	2020-09-21	59.557 mi
Registration #14	2021-09-21	63.557 mi
Registration #15	2022-09-21	67.557 mi
Registration #16	2023-09-21	71.557 mi
Registration #17	2024-09-21	75.557 mi
Registration #18	2025-09-21	79.557 mi
Registration #19	2026-09-21	83.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118