



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE EU4
Colour	Green
Year of manufacture	2005
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	239 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-05-24
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	39
Total items failed	8

MOT #16	2020-09-10 16:08
MOT test number	948337622541
Result	✓ Passed
Next expiry date	2021-09-19
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside mirror insecure
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2020-09-09 12:47

MOT test number

115086947768

Result**✗ Failed****Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Horn not working (7.7 (a) (ii))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside mirror insecure**Fail** Offside Obligatory mirror insecure (3.3 (b) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #14**

2019-09-20 08:08

MOT test number

515248529441

Result**✓ Passed****Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Rear light outer casing damaged**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #13	2019-09-19 11:23
MOT test number	560114315945
Result	✗ Failed
Fail	Nearside Rear Rear reflector missing (4.8.2 (a) (ii))
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Nearside Rear light outer casing damaged
Advice	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2017-10-17 10:49
MOT test number	483110341702
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



MOT #11 2017-10-10 09:55

MOT test number 725013585431

Result ✗ Failed

- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #10 2016-10-28 08:32

MOT test number 511959913782

Result ✓ Passed

- Advice** Nearside Rear Exhaust has a minor leak of exhaust gases silencer broken (7.1.2)
- Advice** Nearside Rear brake disc pitted

MOT #9 2015-09-22 13:22

MOT test number 900843437536

Result ✓ Passed

- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2014-10-22 14:03**MOT test number** 535145894259**Result** ✓ Passed

- Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2013-01-03 15:07**MOT test number** 125863703065**Result** ✓ Passed**MOT #6** 2011-10-28 11:11**MOT test number** 388341401336**Result** ✓ Passed**MOT #5** 2010-10-27 16:21**MOT test number** 441150000391**Result** ✓ Passed**MOT #4** 2010-10-27 12:03**MOT test number** 280390500399**Result** ✗ Failed

- Fail** Exhaust system not adequately supported (7.1.1)



MOT #3	2009-11-25 16:16
MOT test number	293579429332
Result	✓ Passed

MOT #2	2009-11-25 13:01
MOT test number	821969629398
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Rear brake disc slightly pitted (3.5.1h)

MOT #1	2008-11-27 13:56
MOT test number	173742138396
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
2 April 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-11-10
Last registration	2020-09-10
Complete history	See info



Registration #1	2005-11-10	18 mi
Registration #2	2008-11-27	40.256 mi
Registration #3	2009-11-25	52.256 mi
Registration #4	2009-11-25	52.256 mi
Registration #5	2010-10-27	63.222 mi
Registration #6	2010-10-27	63.222 mi
Registration #7	2011-10-28	75.703 mi
Registration #8	2013-01-03	88.803 mi
Registration #9	2014-10-22	105.418 mi
Registration #10	2015-10-22	121.277 mi
Registration #11	2016-10-22	137.136 mi
Registration #12	2017-10-22	152.995 mi
Registration #13	2018-10-22	168.854 mi
Registration #14	2019-10-22	184.713 mi
Registration #15	2020-09-10	199.572 mi
Registration #16	2020-09-10	199.572 mi
Registration #17	2020-09-10	199.572 mi
Registration #18	2020-09-10	199.572 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2110 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2043 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	331761