






### General information

Make	HONDA
Model	CR-V I-DTEC EX
Colour	Silver
Year of manufacture	2018
Top speed	125 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	158 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	55.4 mpg
CO2 emission	133 g/km
CO2 label	E







Internet history	
Entry 1	
Date	2021-08-04
Pictures	0
Listing price	View report

source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-28
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	15
Total items failed	0

MOT #4		2024-03-01 09:28
MOT test number		474816525875
Result		✓ Passed
Next expiry date		2025-03-28
Advice Offside F	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Bra	ake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside	e Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

# MOT #3

Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

2023-03-08 09:28 713588295028



Ν	U18GVM
	report date: 2024-03-29

MOT #2	2022-03-04 09:23
MOT test number	416640893551
Result	✓ Passed
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	
MOT #1	2021-03-18 16:06
MOT test number	977960039965

mor test	977900039903
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

√ Taxed	✓ МОТ	
Tax due: 1 November 2024	Expires: 28 March 2025	
Tax status	Valid until 1 November	
Days left	186	
MOT expiry date 28 March 202		
Full MOT history	See MOT history	

## Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this HONDA had different number plates	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-03-29
Last registration	2024-03-01
Complete history	See info



Registration #1	2018-03-29	22 mi
Registration #2	2021-03-18	30.914 mi
Registration #3		11.777 esi
Registration #4		11.777 esi
Registration #5		11.227 mi
Registration #6		11.117 esi





# Safety ratings

NCAP rating	****
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	2095 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1718 kg
Max. allowed weight	2170 kg
Additional information	
Additional information Fuel tank capacity	58 I
	58 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5