



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI (90BHP) LX
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	51.4 mpg






LABEL UNKNOWN



Internet history

Entry 3

Date	2021-09-18
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 2

Date	2021-09-18
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-09-17
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #25	2022-11-21 15:50
MOT test number	203962527329
Result	✓ Passed
Next expiry date	2023-11-20
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii))
Advice	Front tyres worn on edges
Advice	Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #24	2022-11-15 11:58
MOT test number	356761299156
Result	✗ Failed
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Front tyres worn on edges
MAJOR	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #23**

2021-11-10 14:43

MOT test number

315600717046

Result

✓ Passed

- Advice** Coil spring corroded (5.3.1 (b) (i))
- Advice** Lift top sturts
- Advice** Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Play in steering rack inner joint(s)
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Wheel trims
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #22**

2021-11-09 15:37

MOT test number

205679854440

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Lift top sturts
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- MAJOR** Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Wheel trims
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))
- DANGEROUS** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Play in steering rack inner joint(s)

**MOT #21** 2020-09-17 08:55**MOT test number** 616610200570**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #20** 2019-08-21 09:12**MOT test number** 267080228610**Result** ✓ Passed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19** 2018-09-19 07:19**MOT test number** 840949137465**Result** ✓ Passed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18**

2018-09-18 08:26

MOT test number

400230960763

Result**✗ Failed**

- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- MAJOR** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a))

MOT #17

2017-09-05 08:06

MOT test number

898684183274

Result**✓ Passed**

- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)



MOT #16

2016-08-18 07:27

MOT test number

828969676799

Result

✓ Passed

- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice

Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice

Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**MOT #15**

2016-08-17 08:29

MOT test number

228730116145

Result**✗ Failed****Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #14**

2015-08-21 09:21

MOT test number

219581511834

Result**✓ Passed****Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Slight corrosion around both rear bump stops.

**MOT #13** 2014-08-20 12:31**MOT test number** 258832734200**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #12** 2014-08-19 09:00**MOT test number** 559471534201**Result** ✗ Failed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #11** 2013-08-30 15:33**MOT test number** 195662043297**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2013-08-29 17:14**MOT test number** 578281843208**Result** ✗ Failed**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9**

2012-09-04 14:04

MOT test number

926398542217

Result

✓ Passed

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice

Front brake discs wearing thin

Advice

Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice

Rear brake pad wear getting low

MOT #8

2011-09-17 10:01

MOT test number

288860261210

Result

✓ Passed

Notice

Front brake discs worn

Notice

Coolant leak

Notice

Rear brake discs in poor condition

MOT #7

2011-09-17 10:01

MOT test number

228970161215

Result

✗ Failed

Notice

Front brake discs worn

Notice

Coolant leak

Pass with rectification

Registration plate lamp not working (1.1.C.1d)

Notice

Rear brake discs in poor condition

**MOT #6** 2010-07-30 09:23**MOT test number** 834221510228**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2010-07-30 09:23**MOT test number** 632231810226**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2009-07-31 09:59**MOT test number** 360962419219**Result** ✓ Passed**MOT #3** 2008-08-05 18:38**MOT test number** 313638218234**Result** ✓ Passed**MOT #2** 2007-07-28 08:19**MOT test number** 800699307222**Result** ✓ Passed



MOT #1	2006-08-07 15:35
MOT test number	553819916252
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2002-08-01
Last registration	2022-11-21
Complete history	See info



Registration #1	2002-08-01	16 mi
Registration #2	2006-08-07	32.322 mi
Registration #3	2007-07-28	38.194 mi
Registration #4	2008-08-05	46.855 mi
Registration #5	2009-07-31	53.949 mi
Registration #6	2010-07-30	60.954 mi
Registration #7	2011-09-17	67.290 mi
Registration #8	2012-09-04	71.480 mi
Registration #9	2013-08-29	75.181 mi
Registration #10	2013-08-30	75.201 mi
Registration #11	2014-08-19	79.722 mi
Registration #12	2014-08-20	79.731 mi
Registration #13	2015-08-21	84.117 mi
Registration #14	2016-08-17	88.003 mi
Registration #15	2016-08-17	88.003 mi
Registration #16	2016-08-17	88.003 mi
Registration #17	2016-08-17	88.003 mi
Registration #18	2016-08-17	88.003 mi
Registration #19	2016-08-17	88.003 mi
Registration #20	2016-08-17	88.003 mi
Registration #21	2016-08-17	88.003 mi
Registration #22	2016-08-17	88.003 mi
Registration #23	2016-08-17	88.003 mi
Registration #24	2016-08-17	88.003 mi
Registration #25	2016-08-17	88.003 mi
Registration #26	2016-08-17	88.003 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1975 mm
Height	1420 mm
Length	4354 mm
Wheel base	2540 mm
Kerb weight	1166 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DYJM3018426