



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | FORD           |
| Model               | KA ZETEC       |
| Colour              | Red            |
| Year of manufacture | 2009           |
| Top speed           | 99 mph         |
| 0 - 60 mph          | 13.1 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 68 BHP              |
| Max. torque             | 102 Nm at 3.000 rpm |
| Engine capacity         | 1.242 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 44.8 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 55.4 mpg            |
| CO2 emission            | 119 g/km            |
| CO2 label               | C                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-07                  |
| Pictures      | 4                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-07-23 |
| MOT pass rate      | 81 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 3          |
| Total advice items | 41         |
| Total items failed | 2          |

|                  |  |
|------------------|--|
| MOT #16          | 2023-07-24 15:58   |
| MOT test number  | 757986241319   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-07-23   |
| Minor            | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

**MOT #15**

2023-07-11 09:29

**MOT test number**

568317559160

**Result****✗ Failed**

- MAJOR** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases joint (6.1.2 (a))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Brake cable insecure (1.1.15 (c))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2023-03-15 11:35

**MOT test number**

979219009772

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2022-03-21 14:31

**MOT test number**

110538221036

**Result**

✓ Passed

**MOT #12**

2021-03-29 07:46

**MOT test number**

249768226482

**Result**

✓ Passed

- Advice** Engine bay covers and under body trays

**MOT #11**

2020-03-24 16:03

**MOT test number**

989961292924

**Result**

✓ Passed

- Advice** Offside Rear Coil spring corroded at bottom (5.3.1 (b) (i))
- Advice** Engine bay covers
- Advice** Nearside Rear Coil spring corroded at bottom (5.3.1 (b) (i))

**MOT #10** 2019-03-27 14:26**MOT test number** 230434854508**Result** ✓ Passed**MOT #9** 2018-03-22 11:22**MOT test number** 566234330110**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin both front pads (3.5.1g)
- Advice** Engine bay covers and under body trays
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (3.5.1i)

**MOT #8** 2018-03-22 08:51**MOT test number** 387341402880**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin both front pads (3.5.1g)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (3.5.1i)
- Advice** Engine bay covers and under body trays

**MOT #7** 2017-03-30 14:26**MOT test number** 204522751068**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear exhaust box rusty
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2017-03-30 10:47**MOT test number** 421328998808**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear exhaust box rusty**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2016-03-30 10:29**MOT test number** 978017111722**Result** ✓ Passed**Advice** Rear silencer starting to corrode**MOT #4** 2015-03-24 10:05**MOT test number** 745883485035**Result** ✓ Passed**MOT #3** 2014-03-28 09:26**MOT test number** 767217984012**Result** ✓ Passed**MOT #2** 2013-03-27 08:43**MOT test number** 969326183049**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-03-29 15:47**MOT test number** 805219982051**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
23 July 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 October           |
| <b>Days left</b>        | 154                             |
| <b>MOT expiry date</b>  | 23 July 2024                    |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 48             |
| <b>Band</b>                                    | C              |
| <b>Single payment (12 months)</b>              | £ 35,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 36,75,-      |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | WJ09XXN    |
| Plate since          | 2019-03-29 |
| Current registration | WJ09XXN    |
| Plate since          | 2019-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2009-03-30               |
| Last registration          | 2023-07-24               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-03-30 | 10 mi     |
| Registration #2  | 2012-03-29 | 24.601 mi |
| Registration #3  | 2013-03-27 | 34.533 mi |
| Registration #4  | 2014-03-28 | 42.328 mi |
| Registration #5  | 2015-03-24 | 45.226 mi |
| Registration #6  | 2016-03-30 | 48.024 mi |
| Registration #7  | 2017-03-30 | 49.001 mi |
| Registration #8  | 2017-03-30 | 49.001 mi |
| Registration #9  | 2018-03-22 | 50.318 mi |
| Registration #10 | 2019-03-29 | 51.337 mi |
| Registration #11 | 2019-03-29 | 51.337 mi |
| Registration #12 | 2019-03-29 | 51.337 mi |
| Registration #13 | 2019-03-29 | 51.337 mi |
| Registration #14 | 2019-03-29 | 51.337 mi |
| Registration #15 | 2019-03-29 | 51.337 mi |
| Registration #16 | 2019-03-29 | 51.337 mi |
| Registration #17 | 2019-03-29 | 51.337 mi |
| Registration #18 | 2019-03-29 | 51.337 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1702 mm |
| Height              | 1505 mm |
| Length              | 3620 mm |
| Wheel base          | 2300 mm |
| Kerb weight         | 940 kg  |
| Max. allowed weight | 1320 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 4                     |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | 5187434 |