





report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO SPORT TJET
Colour	Grey
Year of manufacture	2010
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2022-01-26	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$			
10.71	α	h	sto	rv
101	() I		510	II V
	•		-	. ,

MOT expiry date	2025-02-14
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #15	2024-02-14 10:22
MOT test number	704935528391
Result	✓ Passed
Next expiry date	2025-02-14
Advice FRONT LIGHTS NEED POLISHING	

MOT #14	2023-02-14 16:51
MOT test number	757673530830
Result	✓ Passed
MOT #13	2022-02-15 15:35
MOT test number	699068284343
Result	✓ Passed
MOT #12	2021-01-15 16:16
MOT test number	563750432359
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #11 2021-01-14 15:29

MOT test number 305917601983

Result

× Failed

Fail Nearside Front Suspension arm pin or bush excessively worn Lower suspension arm rear bush worn to excess (5.3.4 (a) (i))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #10 2020-01-31 14:22

MOT test number 717100482842

Result

Passed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight leak (6.1.7 (g) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres on 2.0mm (5.2.3 (e))

MOT #9 2020-01-30 15:34

MOT test number 588233449611

Result X Failed

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight leak (6.1.7 (g) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn Lower wishbone rear bush worn to excess (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres on 2.0mm (5.2.3 (e))

MOT #8 2019-01-25 13:37

MOT test number 737186864787

Result

Passed

Advice Rear Registration plate deteriorated but not likely to be misread damaged (0.1 (b))

Advice Rear exhaust outer skin corroded

CarCheck.co.uk page 4/13



MOT test number

Result

Pass with rectification

Offside Front Headlamp aim too low (4.1.2 (a))

Pass with rectification

Nearside Front Headlamp aim too low (4.1.2 (a))

Advice

Rear Registration plate deteriorated but not likely to be misread damaged (0.1 (b))

Advice

Rear exhaust outer skin corroded

MOT #6	2018-02-01 08:38
MOT test number	566877806821
Result	✓ Passed
MOT #5	2017-04-19 09:33
MOT test number	204398626251
Result	✓ Passed
MOT #4	2016-04-29 13:35
MOT test number	411851314792
Result	✓ Passed
MOT #3	2015-04-08 08:48
MOT test number	745328295078
Result	✓ Passed
MOT #2	2014-05-01 09:54
MOT test number	129671124126
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2013-03-05 11:59

MOT test number 497984263053

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
THE PARTY OF THE P	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-12
Last registration	2024-02-14
Complete history	See info



Registration #1	2010-03-12	15 mi
Registration #2	2013-03-05	16.433 mi
Registration #3	2014-05-01	20.136 mi
Registration #4	2015-04-08	23.586 mi
Registration #5	2016-04-29	28.154 mi
Registration #6	2017-04-19	32.689 mi
Registration #7	2018-02-01	37.272 mi
Registration #8	2019-01-25	44.543 mi
Registration #9	2019-01-25	44.543 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		77.777 au

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles2Engine number1229357