





report date: 2024-03-29

General information

Make	MAZDA
Model	CX-30 GT SPORT
Colour	Grey
Year of manufacture	2020
Top speed	116 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	213 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	45.6 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-04-14

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-15
MOT pass rate	50 %
MOT passed	2
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #4		2024-03-02 12:47
MOT test	number	583844528586
Result		✓ Passed
Next expi	ry date	2025-03-15
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #3		2024-03-02 10:44
MOT test	number	720679499982
Result		× Failed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



MOT #2 2023-03-11 11:24

MOT test number 972209242014

Result ✓ Passed

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #1 2023-03-11 10:30

MOT test number 672218758750

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2020-03-16
Last registration	2024-03-02
Complete history	See info



Registration #1	2020-03-16	24 mi
Registration #2		71,777 66
Registration #3	2023-03-11	17.964 mi
Registration #4		71,777 66
Registration #5		11,777 mi
Registration #6		11.777 es

More info >

page 10/11 CarCheck.co.uk



Safety ratings

NCAP rating	****
Adult	99%
Children	86%
Pedestrian	80%
Safety systems	77%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1540 mm
Length	4395 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	PE 21411050

CarCheck.co.uk page 11/11