



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PRIUS VVT-I T SPIRIT
Colour	Black
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	70.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-05
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-03-13
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	33
Total items failed	11

**MOT #18** 2024-03-14 15:06**MOT test number** 690030608426**Result** ✓ Passed**Next expiry date** 2025-03-13**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge very close to cords on inner edge (5.2.3 (e))**MOT #17** 2024-03-05 14:18**MOT test number** 459944307388**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Front Exhaust mounting defective rubber mounting broken (6.1.2 (a))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge very close to cords on inner edge (5.2.3 (e))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (5.2.3 (d) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #16** 2023-07-18 10:47**MOT test number** 172636325320**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge both edges (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge - very close to exposing cords (5.2.3 (e))**MOT #15** 2023-03-15 10:46**MOT test number** 840793852237**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #14** 2022-03-22 10:57**MOT test number** 585977104275**Result** ✓ Passed**MOT #13** 2022-03-21 16:57**MOT test number** 921849305528**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2021-03-15 14:45**MOT test number** 300149842427**Result** ✓ Passed

**MOT #11** 2020-05-20 14:59**MOT test number** 344232952255**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front both sides, shock absorber boots are starting to perish**Advice** Rear coil springs both sides have slight surface corrosion on them.**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear chassis sections have some surface corrosion on them.**MOT #10** 2020-05-20 14:59**MOT test number** 213061264999**Result** ✗ Failed**Advice** Rear chassis sections have some surface corrosion on them.**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front both sides, shock absorber boots are starting to perish**Advice** Rear coil springs both sides have slight surface corrosion on them.**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-05-17 09:14**MOT test number** 666709604923**Result** ✓ Passed**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))



<b>MOT #8</b>	2019-05-17 09:14
<b>MOT test number</b>	900920934125
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Pass with rectification</b>	Front Registration plate inscription illegible (0.1 (b))

<b>MOT #7</b>	2018-05-23 10:40
<b>MOT test number</b>	353256233509
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre wearing/cracking on sidewall no cords exposed
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Rear Tyre wearing/cracking on sidewall no cords exposed
<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #6</b>	2017-04-28 13:54
<b>MOT test number</b>	733213027778
<b>Result</b>	✓ Passed
<b>Advice</b>	Front registration plate deteriorated but not likely to be misread (6.3.1d)
<b>Advice</b>	Both rear tyres have slight surface cracking on them.

<b>MOT #5</b>	2017-04-28 13:54
<b>MOT test number</b>	770459241100
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
<b>Advice</b>	Both rear tyres have slight surface cracking on them.
<b>Advice</b>	Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #4	2016-05-10 13:09
MOT test number	385513736384
Result	✓ Passed
MOT #3	2015-05-19 15:57
MOT test number	885629135168
Result	✓ Passed
MOT #2	2014-05-22 10:59
MOT test number	145212044106
Result	✓ Passed
Notice	Cuts in nearside front tyre outer sidewall
MOT #1	2013-05-10 09:30
MOT test number	946660433179
Result	✓ Passed
Notice	Slight scuffs on both front tyres
Notice	Slight surface cracking on both rear tyres



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
13 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	13 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-05-27
Last registration	2024-03-14
Complete history	<a href="#">See info</a>



Registration #1	2010-05-27	14 mi
Registration #2	2013-05-10	25.009 mi
Registration #3	2014-05-22	32.802 mi
Registration #4	2015-05-19	39.541 mi
Registration #5	2016-05-10	46.230 mi
Registration #6	2017-04-28	52.875 mi
Registration #7	2017-04-28	52.875 mi
Registration #8	2018-05-23	61.010 mi
Registration #9	2019-05-17	70.039 mi
Registration #10	2019-05-17	70.039 mi
Registration #11	2019-05-17	70.039 mi
Registration #12	2019-05-17	70.039 mi
Registration #13	2019-05-17	70.039 mi
Registration #14	2019-05-17	70.039 mi
Registration #15	2019-05-17	70.039 mi
Registration #16	2019-05-17	70.039 mi
Registration #17	2019-05-17	70.039 mi
Registration #18	2019-05-17	70.039 mi
Registration #19	2019-05-17	70.039 mi
Registration #20	2019-05-17	70.039 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1745 mm
Height	1490 mm
Length	4460 mm
Wheel base	2700 mm
Kerb weight	1420 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

1ZX4490943