





General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg





Internet history

Entry 1			
Date	2021-06-1	1	
Pictures	9		
Listing price	View repor	<u>t</u>	
★ Trustpilot	AvertROED		Reserve



* * * * *







source: autotrader.co.uk



MOT history

MOT #16

BF55VWD		BF55VWD
report date: 2024-03-29		report date: 2024-03-29
2020-11-13 12:04	4	2020-11-13 12:04

MOT test number	396082380902
Result	✓ Passed
Next expiry date	2021-11-17
MOT #15	2019-05-15 10:32
MOT test number	343551809653
Result	✓ Passed
MOT #14	2018-05-18 11:37
MOT test number	876921723652
Result	✓ Passed
MOT #13	2017-05-17 11.47

MUT #13	2017-05-17 11:47
MOT test number	922202326486
Result	✓ Passed

MOT #12	2016-05-09 11:23
MOT test number	481867708212
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal lim	it (4.1.E.1)

MOT #11	2015-05-02 11:40
MOT test number	609142825119
Result	✓ Passed





MOT #10		2015-05-02 11:40
MOT test number		755772225158
Result		🗙 Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #9		2014-05-13 13:03
MOT test	number	159883334147
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Nearside rear tyre is cracked and perished	
Notice	Oil leak	
MOT #8		2013-04-30 15:06

MOT test number	269980323493
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #7	2013-04-30 13:10	
MOT test number	978630823192	
Result	🗙 Failed	
Fail Rear registration plate delaminated (6.3.1d)		
Advice Nearside Front Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)		
Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)		
Fail Front registration plate has a feature which changes the appearance or legibility of (6.3.4c)	f the characters	
Notice Oil leak		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		

MOT #6	2012-07-13 09:09
MOT test number	369785592178
Result	✓ Passed
Notice Child seat fitted to nearside rear seat	

MOT #5	2011-07-18 15:37
MOT test number	436489591104
Result	Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2011-07-18 10:13
MOT test number	889569491175
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Rear Exhaust system not adequately supported (7.1.1)	





MOT #3		2010-07-21 16:44
MOT test	number	240642500230
Result		Passed
MOT #2		2009-09-04 13:12
MOT test	number	512677949224
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #1		2008-12-10 16:53
MOT test	number	610015548383
Result		✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMPL
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-09-30
Last registration	2020-11-13
Complete history	See info



Registration #1	2005-09-30	29 mi
Registration #2	2008-12-10	77.934 mi
Registration #3	2009-09-04	87.260 mi
Registration #4	2010-07-21	88.084 mi
Registration #5	2011-07-18	95.277 mi
Registration #6	2011-07-18	95.277 mi
Registration #7	2012-07-13	102.409 mi
Registration #8	2013-04-30	108.605 mi
Registration #9	2013-04-30	108.606 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi



Safety ratings		
NCAP rating		0
Video	see crash video	
Dimensions & weight		
Width		1751 mm
Height		1637 mm
Length		4276 mm
Wheel base		2760 mm
Kerb weight		1300 kg
Max. allowed weight		1850 kg
Additional information		
Fuel tank capacity		60 I
Fuel delivery		Direct Injection
Number of doors		5
Number of seats		5
Engine number		DYUF4010622