





report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I ROADSTER
Colour	Red
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-02-01	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	26
Total items failed	3

MOT #16	2023-10-02 08:07
MOT test number	282247281255
Result	✓ Passed
Next expiry date 2024-10-0	
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords various cuts inner sidewall (5.2.3 (d) (i)) Advice Front Oil leak, but not excessive engine (8.4.1 (a) (i))	

MOT #15		2023-10-02 08:07
MOT test number		612164341428
Result		X Failed
Pass with rectification	Nearside Front Position lamp not working	ng (4.2.1 (a) (ii))
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords various cuts inner sidewall (5.2.3 (d) (i))		
Advice Front Oil leak, but not excessive engine (8.4.1 (a) (i))		

CarCheck.co.uk page 3/13



Minor

Advice

LB08LCK report date: 2024-03-28

MOT #14

MOT test number

Result

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT test number

Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT test number

557716686247

Result

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11 2020-09-10 08:45

MOT test number 651412954078

Result ✓ Passed

CarCheck.co.uk page 4/13



LB08LCK

report date: 2024-03-28

MOT #10	2019-10-02 10:06
MOT test number	109422011725
Result	✓ Passed
Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I)) Advice Nearside Rear Nail in tyre	

MOT #9		2019-10-02 10:06
MOT test number		888339219683
Result		X Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear Nail in tyre		
Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))		

MOT #8	2018-10-09 11:38
MOT test number	934385565189
Result	✓ Passed
MOT #7	2017-09-08 08:01
MOT test number	912157231953
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6		2016-09-03 10:22
MOT test	number	582479453290
Result		✓ Passed
Advice	Rear Inner Brake pad(s) wearing thin (3.5.1g)	
Advice	Engine covers and under trays fitted to the vehicle	

CarCheck.co.uk page 5/13



MOT #5 2015-09-04 12:36

MOT test number 957010261348

MOT #4 2014-08-14 09:52

MOT test number 488396324241

Result
✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2013-08-29 12:37

MOT test number 849261143293

Result ✓ Passed

MOT #2 2012-09-14 15:44

MOT test number 717028352247

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Nail in offside rear tyre

MOT #1 2011-06-27 10:53

MOT test number 647388971122

Result ✓ Passed

Notice Oil leak

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-01
Last registration	2023-10-02
Complete history	See info



Registration #1	2008-07-01	27 mi
Registration #2	2011-06-27	21.662 mi
Registration #3	2012-09-14	30.482 mi
Registration #4	2013-08-29	34.197 mi
Registration #5	2014-08-14	37.953 mi
Registration #6	2015-09-04	43.728 mi
Registration #7	2016-09-03	50.541 mi
Registration #8	2017-09-08	56.657 mi
Registration #9	2018-10-09	61.869 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1155 kg
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	L8 20260874

CarCheck.co.uk page 13/13