





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	A A 200 AMG LINE EXECUTIVE
Colour	Grey
Year of manufacture	2019
Top speed	140 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	120 kW / 163 HP / 161 BHP
Max. torque	250 Nm at 1.620 rpm
Engine capacity	1.332 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-11-14

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 1

Date 2022-06-16


Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-27
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #7		2023-12-28 15:27
MOT test i	number	965164000575
Result		✓ Passed
Next expir	y date	2024-12-27
Advice	Items removed from driver's view prior to test	
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner edge	worn (5.2.3 (e))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing damage side wall	l (5.2.3 (d) (ii))
Advice Nearside Front Tyre slightly damaged all over tread area (5.2.3 (d) (ii))		
Advice	Nearside Front Nail in tyre	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice (a) (ii))	Nearside Rear Brake pad(s) wearing thin can't see inner Brake pad's look ri	ght on limit?? (1.1.13
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cord	s (5.2.3 (d) (i))

CarCheck.co.uk page 3/12



GY19YFV

report date: 2024-03-29

MOT #6	2023-12-19 17:44
MOT test number	632098814717
Result	X Failed
Advice Nearside Front Tyre slightly damaged all over tread area (5.2.3 (d) (ii)))
Advice Items removed from driver's view prior to test	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Rear Brake pad(s) wearing thin can't see inner Brake pad's la (a) (ii))	ook right on limit?? (1.1.13
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or	r cords (5.2.3 (d) (i))
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner	edge worn (5.2.3 (e))
Advice Nearside Front Nail in tyre	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #5	2022-12-21 15:37
MOT test number	365366254789
Result	✓ Passed
MOT #4	2022-12-21 11:53
MOT test number	690079911631
Result	× Failed
Fail Offside Rear Seat belt buckle missing (7.1.2 (d))	

MOT #3		2022-05-02 17:50
MOT test	number	206069631320
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))	

CarCheck.co.uk page 4/12



GY19YFV

report date: 2024-03-29

 MOT #2
 2022-04-16 12:17

 MOT test number
 669639995260

 Result
 ✓ Passed

 MOT #1
 2022-04-02 14:15

 MOT test number
 572557905832

 Result
 X Failed

 Fail
 Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



GY19YFV

report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2019-03-29
Last registration	2023-12-28
Complete history	See info



Registration #1	2019-03-29	20 mi
Registration #2	2022-04-02	49.315 mi
Registration #3	2022-04-16	49.704 mi
Registration #4	2022-05-02	49.873 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	91%
Pedestrian	92%
Safety systems	75%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1796 mm
Height	1440 mm
Length	4419 mm
Wheel base	2729 mm
Kerb weight	1375 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	28291480130682