






report date: 2024-03-29

### General information

Make	FORD
Model	FUSION
Colour	Green
Year of manufacture	-
Gearbox	-

# Engine & fuel consumption

Fuel type Petrol



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-09-04

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



### **MOT** history

MOT #23		2023-06-15 10:30
MOT test	number	626207210297
Result		✓ Passed
Next expi	ry date	2024-06-14
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Coolant leak	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	<b>(2)</b>
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	)
Advice	Aux belt deteriorated	

MOT #22		2023-06-14 12:44
MOT test	number	974741319683
Result		<b>×</b> Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Aux belt deteriorated	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR	Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))	
Advice	Coolant leak	
MAJOR	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	

CarCheck.co.uk page 3/13



(b))

KJ53ZGF report date: 2024-03-29

**MOT #21** 2022-09-06 11:52 265639637339 **MOT** test number ✓ Passed Result **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

MOT #20	2021-09-02 11:24
MOT test number	990030075601
Result	<b>✓</b> Passed
MOT #19	2020-10-02 11:46
MOT test number	244633332628
Result	<b>√</b> Passed

MOT #18		2019-10-17 15:32
MOT test	number	278534880319
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (	c))
Advice	Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))	

CarCheck.co.uk page 4/13



MOT test number

Result

Advice

Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MAJOR

Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Brake pipe corroded, covered in grease or other material all original (1.1.11 (c))

MOT test number
938907378415

Result

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake pipe corroded, covered in grease or other material all original (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

MOT test number

585793407086

Result

Advice Brake pipe slightly corroded both front to rears (3.6.B.2c)

CarCheck.co.uk page 5/13



Result

KJ53ZGF
report date: 2024-03-29

✓ Passed

MOT #13

MOT test number

Result

Advice Brake pipe slightly corroded all original (3.6.B.2c)

 MOT #12
 2015-10-23 13:35

 MOT test number
 958921499020

 Result
 ✓ Passed

 MOT #11
 2014-10-13 15:40

 MOT test number
 698046984200

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #10
 2013-10-14 14:51

 MOT test number
 316207683466

 Result
 ✓ Passed

 MOT #9
 2013-10-14 14:51

 MOT test number
 698567983269

 Result
 X Failed

 Pass with rectification
 Offside Rear Stop lamp not working (1.2.1b)

 MOT #8
 2012-10-19 11:49

 MOT test number
 479063092215

 Result
 ✓ Passed

 MOT #7
 2011-10-04 15:18

 MOT test number
 597837671270

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



MOT #6	2010-10-06 15:48
MOT test number	793329470295
Result	<b>✓</b> Passed
MOT #5	2009-10-14 15:42
MOT test number	331387989290
Result	✓ Passed
MOT #4	2008-10-21 12:04
MOT test number	922785698200
Result	✓ Passed
MOT #3	2007-10-10 15:15
MOT test number	252953687267
Result	✓ Passed
MOT #2	2006-10-31 14:56
MOT test number	480814606498
Result	✓ Passed
MOT #1	2006-09-13 08:26
MOT test number	533686156214
Result	✓ Passed

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



e when miscory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	*****
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-19
Last registration	2023-06-15
Complete history	See info



21 mi 5-09-19 20.892 mi 5-10-31 21.342 mi 7-10-10 24.629 mi 3-10-21 26.565 mi 9-10-14 28.055 mi 0-10-06 31.760 mi
21.342 mi 7-10-10 24.629 mi 3-10-21 26.565 mi 9-10-14 28.055 mi
7-10-10 24.629 mi 3-10-21 26.565 mi 9-10-14 28.055 mi
26.565 mi 9-10-14 28.055 mi
9-10-14 28.055 mi
)-10-06 31.760 mi
= 2.1.00 1.11
1-10-04 33.614 mi
2-10-19 34.729 mi
35.390 mi
4-10-13 36.306 mi
5-10-23 37.294 mi
10.0
1.07 m
1.07 m
1.07 m
10.0
10.0
10.0
1.01.0
1.07 m
1.00.00
3 4 5

More info >



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Additional information

Engine number 3E09767

CarCheck.co.uk page 13/13