



OV57PWK


report date: 2024-03-29

General information

Make	AUDI
Model	TT TFSI
Colour	Grey
Year of manufacture	2007
Top speed	149 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	200 BHP
Max. torque	280 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-01-28
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-22
Pictures	20
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-01-03
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #16 2024-01-04 12:04

MOT test number 368401341787

Result ✓ Passed

Next expiry date 2025-01-03

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2022-10-22 10:55

MOT test number 420747582735

Result ✓ Passed

MOT #14 2021-12-07 16:19

MOT test number 262057452403

Result ✓ Passed

**MOT #13** 2020-12-09 09:53**MOT test number** 907123749534**Result** ✓ Passed**Advice** Both rear shock absorbers corroded**Advice** Undertrays fitted**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**MOT #12** 2019-12-11 09:10**MOT test number** 436256523462**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2018-12-07 10:46**MOT test number** 410083159155**Result** ✓ Passed**Advice** Engine covers fitted not allowing full visual inspection**Advice** O/s mirror glass loose**Advice** Both front tyres worn on inner edges and cracked between tread patterns**MOT #10** 2017-12-13 11:00**MOT test number** 363529967282**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Both rear tyres low tread & inner edges worn**Advice** Shock absorber has slight corrosion to the casing both rears (2.7.2a)**Advice** Under trays & under covers fitted to vehicle

**MOT #9** 2016-11-23 08:02**MOT test number** 470253010671**Result** ✓ Passed**MOT #8** 2015-11-19 12:58**MOT test number** 855799207569**Result** ✓ Passed**MOT #7** 2014-12-19 11:28**MOT test number** 689723654318**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-12-19 11:28**MOT test number** 207743454329**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-11-14 07:43**MOT test number** 275668113373**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** All tyres treads cracked

**MOT #4** 2012-12-03 09:25**MOT test number** 708958832314**Result** ✓ Passed**Notice** Nearside cv boot leaking**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-12-03 09:25**MOT test number** 869148332329**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint is insecure (2.5.C.1b)**Notice** Nearside cv boot leaking**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-11-22 08:06**MOT test number** 706896621388**Result** ✓ Passed**MOT #1** 2010-11-27 08:29**MOT test number** 472461030434**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-11-26
Last registration	2024-01-04
Complete history	See info



Registration #1	2007-11-26	28 mi
Registration #2	2010-11-27	25.448 mi
Registration #3	2011-11-22	29.456 mi
Registration #4	2012-12-03	34.586 mi
Registration #5	2013-11-14	39.182 mi
Registration #6	2014-12-19	44.383 mi
Registration #7	2015-11-19	48.456 mi
Registration #8	2016-11-23	52.362 mi
Registration #9	2017-12-13	56.846 mi
Registration #10	2018-01-01	58.000 mi
Registration #11	2018-01-01	58.000 mi
Registration #12	2018-01-01	58.000 mi
Registration #13	2018-01-01	58.000 mi
Registration #14	2018-01-01	58.000 mi
Registration #15	2018-01-01	58.000 mi
Registration #16	2018-01-01	58.000 mi
Registration #17	2018-01-01	58.000 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1260 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	BWA 113801