



HYI3XNC

report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER SD
Colour	Black
Year of manufacture	2013
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-08-21
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-25
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #10	2023-05-22 13:24
MOT test number	252585869578
Result	✓ Passed
Next expiry date	2024-05-25

MOT #9	2022-05-26 16:49
MOT test number	621981669440
Result	✓ Passed

MOT #8	2021-11-26 10:38
MOT test number	586442757853
Result	✓ Passed

MOT #7	2021-02-15 11:33
MOT test number	157735238094
Result	✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))

**MOT #6** 2021-02-15 09:08**MOT test number** 951319887773**Result** ✗ Failed

DANGEROUS Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))

MOT #5 2020-02-24 11:48**MOT test number** 172283764792**Result** ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4 2019-02-23 10:19**MOT test number** 372167553540**Result** ✓ Passed**MOT #3** 2018-02-12 09:44**MOT test number** 785189744560**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2 2017-02-21 11:06**MOT test number** 646902576755**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2016-02-11 11:06
MOT test number	266692790588
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Nearside Front tyre has several cuts on outer wall but not deep to cords



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
25 May 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-27
Last registration	2023-05-22
Complete history	See info



Registration #1	2013-03-27	11 mi
Registration #2	2016-02-11	11.841 mi
Registration #3	2017-02-21	13.753 mi
Registration #4	2018-02-12	17.797 mi
Registration #5	2019-02-23	22.067 mi
Registration #6	2020-02-24	26.435 mi
Registration #7	2020-05-22	26.577 mi
Registration #8	2020-05-22	26.577 mi
Registration #9	2020-05-22	26.577 mi
Registration #10	2020-05-22	26.577 mi
Registration #11	2020-05-22	26.577 mi
Registration #12	2020-05-22	26.577 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	73108603