



report date: 2024-03-29

General information

Make	JAGUAR
Model	XE R-SPORT AWD
Colour	Black
Year of manufacture	2016
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 3

Date	2022-07-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 2

Date	2022-07-03
Pictures	2
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	8
Total items failed	0

MOT #8	2023-10-19 14:25
MOT test number	710710894270
Result	✓ Passed
Next expiry date	2024-10-19

MOT #7	2022-10-20 11:14
MOT test number	464677283733
Result	✓ Passed

MOT #6	2022-10-19 14:44
MOT test number	667857100051
Result	✗ Failed

DANGEROUS Nearside Rear Inner Brake pad(s) less than 1.5 mm thick ON metal pad backing, touching brake disc surface. (1.1.13 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Scored inner braking surface. (1.1.14 (a) (ii))

Advice Offside Rear Outer Brake pad(s) wearing thin And N/S/R outer also. (1.1.13 (a) (ii))

**MOT #5** 2022-02-04 10:40**MOT test number** 677522496969**Result** ✓ Passed**Advice** Rear Inner Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre slightly damaged/cracking or perishing All four (5.2.3 (d) (ii))**MOT #4** 2021-02-13 09:23**MOT test number** 802314931139**Result** ✓ Passed**MOT #3** 2021-02-08 12:44**MOT test number** 736539527465**Result** ✗ Failed**DANGEROUS** Nearside Front Brake hose damaged and likely to fail fouling on road wheel inner rim (1.1.12 (a))**MOT #2** 2021-01-11 09:51**MOT test number** 606567039291**Result** ✓ Passed**MOT #1** 2019-09-24 13:37**MOT test number** 370924894954**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	OU66NZM
Plate since	2019-09-29
Current registration	OU66NZM
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-10-05
Last registration	2023-10-19
Complete history	See info



Registration #1	2016-10-05	11 mi
Registration #2	2019-09-24	17.753 mi
Registration #3	2021-01-11	22.162 mi
Registration #4	2021-02-08	22.171 mi
Registration #5	2021-02-13	22.174 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		
Registration #12		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	82%
Pedestrian	81%
Safety systems	82%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2075 mm
Height	1416 mm
Length	4672 mm
Wheel base	2835 mm
Kerb weight	1615 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	160518W0781204DTD