




report date: 2024-03-28

## General information

Make	VOLVO
Model	XC90 D5 SE AWD
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.5 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-05-25
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-06-09
<b>MOT pass rate</b>	70 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	18
<b>Total items failed</b>	4

**MOT #10** 2023-06-05 10:36**MOT test number** 741211796572**Result** Passed**Next expiry date** 2024-06-09

- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #9** 2022-06-06 10:30**MOT test number** 722558282368**Result** Passed

- Advice** Both sides front tyres wearing on inner edge
- Advice** Play in steering rack inner joint(s)
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Slight play in both sides front lower suspension arms mounting bush
- Advice** Engine mounting damaged but not to excess (6.1.8 (a) (i))

**MOT #8** 2022-06-06 09:12**MOT test number** 377952595479**Result** ✗ Failed**Fail** Offside Windscreen washer not working (3.5 (a))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Fail** Nearside Windscreen washer not working (3.5 (a))**Advice** Slight play in both sides front lower suspension arms mounting bush**Advice** Play in steering rack inner joint(s)**Advice** Engine mounting damaged but not to excess (6.1.8 (a) (i))**Advice** Both sides front tyres wearing on inner edge**MOT #7** 2021-06-10 14:34**MOT test number** 202404977980**Result** ✓ Passed**MOT #6** 2020-10-27 11:41**MOT test number** 204487851799**Result** ✓ Passed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #5** 2020-10-27 09:04**MOT test number** 657317005910**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #4 2019-10-30 11:15

MOT test number 375091542914

Result ✓ Passed

MOT #3 2019-10-30 11:15

MOT test number 571652465072

Result ✗ Failed

**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #2 2018-10-31 12:31

MOT test number 905335941841

Result ✓ Passed

MOT #1 2017-09-26 15:48

MOT test number 408142873137

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
9 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	9 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-10-12
Last registration	2023-06-05
Complete history	<a href="#">See info</a>



Registration #1	2009-10-12	12 mi
Registration #2	2017-09-26	62.399 mi
Registration #3	2018-10-31	68.239 mi
Registration #4	2019-10-30	75.119 mi
Registration #5	2019-10-30	75.119 mi
Registration #6	2020-10-27	81.503 mi
Registration #7	2020-10-27	81.503 mi
Registration #8	2020-10-27	81.503 mi
Registration #9	2020-10-27	81.503 mi
Registration #10	2020-10-27	81.503 mi
Registration #11	2020-10-27	81.503 mi
Registration #12	2020-10-27	81.503 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1743 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2148 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	741691