



L053PXB


report date: 2024-03-29

General information

Make	SUZUKI
Model	VITARA 16V
Colour	Red
Year of manufacture	2004
Top speed	99 mph
0 - 60 mph	13.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	126 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	34.5 mpg
Consumption combined	22.2 mpg
CO2 emission	250 g/km
CO2 label	L





MOT history

MOT expiry date	2021-07-28
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	27
Total items failed	4

MOT #11	2020-07-29 08:56
MOT test number	475805317893
Result	✓ Passed
Next expiry date	2021-07-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner and outer edges worn (5.2.3 (e))
Advice	Nearside Rear Inner Nail in tyre

MOT #10	2018-10-24 10:13
MOT test number	991386862073
Result	✓ Passed
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake pads wearing low

**MOT #9** 2018-09-20 11:13**MOT test number** 539730991763**Result** ✗ Failed**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (h) (i))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2017-09-21 10:05**MOT test number** 637044307242**Result** ✓ Passed**Advice** Front Nearside and Offside tyre sidewall prish**Advice** Front Nearside and Offside headlamp slight deterioration**MOT #7** 2016-09-06 09:30**MOT test number** 102143305658**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-08-28 15:18**MOT test number** 587970845294**Result** ✓ Passed

**MOT #5** 2014-08-27 11:56**MOT test number** 158239834218**Result** ✓ Passed**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Engine management light stays on**Notice** Both the nearside and the offside rear tyres have sidewall perish and cracked tread**MOT #4** 2014-08-27 11:56**MOT test number** 208289034251**Result** ✗ Failed**Pass with rectification** Battery insecure (1.9.1)**Notice** Engine management light stays on**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Both the nearside and the offside rear tyres have sidewall perish and cracked tread**MOT #3** 2013-08-22 08:44**MOT test number** 868374933210**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-11-20 11:54**MOT test number** 717845722397**Result** ✓ Passed**Notice** Offside rear bumper damaged



MOT #1	2012-11-12 17:18
MOT test number	937927112324
Result	✗ Failed
Advice	Nearside Outer Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Headlamp aim beam image kick up to the offside (1.8)
Fail	Offside Rear fog lamp not working (1.3.2b)
Advice	Offside Outer Front Brake pad(s) wearing thin (3.5.1g)
Notice	Offside rear bumper damaged
Fail	Offside Headlamp aim beam image kick up to the offside (1.8)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	11
First mileage registration	2004-12-31
Last registration	2020-07-29
Complete history	See info



Registration #1	2004-12-31	10 mi
Registration #2	2012-11-12	57.565 mi
Registration #3	2012-11-20	57.703 mi
Registration #4	2013-08-22	37.996 mi
Registration #5	2014-08-27	41.583 mi
Registration #6	2015-08-28	43.508 mi
Registration #7	2016-08-29	55.277 mi
Registration #8	2017-08-30	55.277 mi
Registration #9	2018-08-31	55.277 mi
Registration #10	2019-08-31	55.277 mi
Registration #11	2020-07-29	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1740 mm
Length	4195 mm
Wheel base	2480 mm
Kerb weight	1490 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	J20A-233917