



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Silver
Year of manufacture	2017
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





## Internet history

### Entry 3

Date	2022-05-31
Pictures	43
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 2

Date	2021-09-17
Pictures	3
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 1

Date	2021-09-17
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](https://heycar.co.uk)



MOT history

MOT expiry date	2024-09-04
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	0

MOT #7	2023-09-05 11:18
MOT test number	537174538342
Result	✓ Passed
Next expiry date	2024-09-04

MOT #6	2023-09-04 14:34
MOT test number	789327217651
Result	✗ Failed
MAJOR	Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
MAJOR	Central Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5	2022-09-02 14:55
MOT test number	733351237303
Result	✓ Passed

**MOT #4** 2022-09-02 11:12**MOT test number** 449997612418**Result** ✗ Failed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MAJOR** Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #3** 2021-10-05 14:34**MOT test number** 512904140657**Result** ✓ Passed**MOT #2** 2020-09-29 10:35**MOT test number** 235471704649**Result** ✓ Passed**MOT #1** 2020-03-30 22:14**MOT test number** 951735822026**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2024

✓  
**MOT**

**Expires:**  
4 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	4 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-31
Last registration	2023-09-05
Complete history	<a href="#">See info</a>



Registration #1	2017-03-31	15 mi
Registration #2	2020-09-29	62.271 mi
Registration #3	2019-09-29	25.277 mi
Registration #4	2019-09-29	25.277 mi
Registration #5	2021-10-05	81.265 mi
Registration #6	2019-09-29	25.277 mi
Registration #7	2019-09-29	25.277 mi
Registration #8	2019-09-29	25.277 mi
Registration #9	2019-09-29	25.277 mi
Registration #10	2019-09-29	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M D4 - C257416LQI