



report date: 2024-03-29

## General information

Make	FIAT
Model	PUNTO JTD ACTIVE
Colour	Grey
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-05
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-05-09
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	10
Total items failed	17

MOT #18	2023-05-10 13:26
MOT test number	297058192247
Result	✓ Passed
Next expiry date	2024-05-09

MOT #17	2023-05-10 08:29
MOT test number	592429704677
Result	✗ Failed
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16	2022-02-22 10:12
MOT test number	869123347074
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2021-02-25 12:36**MOT test number** 225596315527**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust corroded**MOT #14** 2020-02-25 15:12**MOT test number** 517663593450**Result** ✓ Passed**MOT #13** 2019-02-21 14:40**MOT test number** 172601156160**Result** ✓ Passed**MOT #12** 2019-02-21 11:56**MOT test number** 794869149526**Result** ✗ Failed**Fail** Offside Front Driver's door catch insecure (6.2.3 (c) (ii))**Fail** Offside Front Windscreen wiper not working (3.4 (a))**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2018-02-27 13:10**MOT test number** 968740813488**Result** ✓ Passed**MOT #10** 2018-02-27 13:10**MOT test number** 159211083521**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



<b>MOT #9</b>	2016-03-11 12:46
<b>MOT test number</b>	673596483647
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #8</b>	2016-03-11 09:11
<b>MOT test number</b>	360912916223
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front coil spring broken (2.4.C.1a)
<b>Fail</b>	Nearside Front Direction indicator incorrect colour (1.4.A.2f)
<b>Fail</b>	Offside Front position lamp(s) not working (1.1.A.3b)
<b>Fail</b>	Nearside Headlamp aim too low (1.8)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b>	Offside Front Direction indicator incorrect colour (1.4.A.2f)
<b>Fail</b>	Offside Headlamp aim too low and too far to the left. (1.8)

<b>MOT #7</b>	2015-03-12 12:08
<b>MOT test number</b>	728101775035
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #6</b>	2014-02-28 11:27
<b>MOT test number</b>	536639254016
<b>Result</b>	✓ Passed

**MOT #5** 2013-03-12 16:26**MOT test number** 218041073086**Result** ✓ Passed**MOT #4** 2012-04-18 09:21**MOT test number** 205549202137**Result** ✓ Passed**MOT #3** 2012-04-18 09:21**MOT test number** 969569902188**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2011-04-20 10:48**MOT test number** 237070611191**Result** ✓ Passed**MOT #1** 2011-04-19 14:33**MOT test number** 279959001138**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
9 May 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	9 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-04-30
Last registration	2023-05-10
Complete history	<a href="#">See info</a>



Registration #1	2008-04-30	10 mi
Registration #2	2011-04-19	27.703 mi
Registration #3	2011-04-20	27.713 mi
Registration #4	2012-04-18	34.704 mi
Registration #5	2013-03-12	39.988 mi
Registration #6	2014-02-28	51.191 mi
Registration #7	2015-03-12	56.373 mi
Registration #8	2016-03-11	59.897 mi
Registration #9	2017-03-11	65.377 mi
Registration #10	2018-03-11	70.377 mi
Registration #11	2019-03-11	75.377 mi
Registration #12	2020-03-11	80.377 mi
Registration #13	2021-03-11	85.377 mi
Registration #14	2022-03-11	90.377 mi
Registration #15	2023-05-10	95.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1090 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	2530568