



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-06-14
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-22
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	28
Total items failed	15

MOT #17	2024-03-20 17:32
MOT test number	504687201506
Result	✓ Passed
Next expiry date	2025-03-22
Advice	Front Shock absorbers has light misting of oil Both shock absorbers. (5.3.2 (b))
Advice	Rear Exhaust is corroded.
Advice	Rear Shock absorbers has light misting of oil Both shock absorbers (5.3.2 (b))
Advice	Rear Shock absorbers has a reduced damping effect Both shock absorbers. (5.3.2 (d))
Advice	Nearside Headlamp has poor output.

**MOT #16**

2024-03-18 10:05

**MOT test number**

864018195824

**Result**

✗ Failed

- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Central Front Exhaust has a major leak of exhaust gases at flexible section. (6.1.2 (a))
- Advice** Rear Shock absorbers has a reduced damping effect Both shock absorbers. (5.3.2 (d))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Steering locking device missing no split pin on track rod end. (2.1.3 (d))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Front Emissions unable to be completed Due to exhaust leak. (8.2.1.2 (d))
- Advice** Nearside Headlamp has poor output.
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Front Shock absorbers has light misting of oil Both shock absorbers. (5.3.2 (b))
- Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt Perishing. (2.1.3 (g) (i))
- Advice** Rear Shock absorbers has light misting of oil Both shock absorbers (5.3.2 (b))
- Fail** Offside Front Steering locking device missing no split pin on track rod end. (2.1.3 (d))
- Advice** Rear Exhaust is corroded.

**MOT #15**

2023-03-23 15:42

**MOT test number**

948524364597

**Result**

✓ Passed

- Advice** Nearside Front headlamp output is poor.
- Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing on failure limit. (5.2.3 (d) (ii))
- Advice** Central Front Exhaust has a minor leak of exhaust gases at flexible section. (6.1.2 (a))

**MOT #14** 2023-03-23 15:42**MOT test number** 441885691916**Result** ✗ Failed**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing on failure limit. (5.2.3 (d) (ii))**Advice** Central Front Exhaust has a minor leak of exhaust gases at flexible section. (6.1.2 (a))**Advice** Nearside Front headlamp output is poor.**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps both bulbs. (4.7.2 (a))**MOT #13** 2022-01-25 15:21**MOT test number** 488032815258**Result** ✓ Passed**MOT #12** 2021-01-28 13:40**MOT test number** 734241885082**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Inner tyre side wall split close to cords.**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2020-01-28 16:08**MOT test number** 802143107244**Result** ✓ Passed

**MOT #10** 2020-01-24 14:26**MOT test number** 489625734929**Result** ✗ Failed**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #9** 2019-01-25 16:53**MOT test number** 753869534125**Result** ✓ Passed**MOT #8** 2018-01-24 15:43**MOT test number** 116813925941**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-09-05 13:00**MOT test number** 760773500009**Result** ✓ Passed**MOT #6** 2016-09-05 12:59**MOT test number** 891612146181**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**MOT #5** 2015-05-16 09:07**MOT test number** 207466635478**Result** ✓ Passed**MOT #4** 2014-06-04 11:48**MOT test number** 898515754109**Result** ✓ Passed**MOT #3** 2013-11-27 15:34**MOT test number** 769101233330**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2013-11-27 15:34**MOT test number** 445051433496**Result** ✗ Failed**Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Pass with rectification** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #1** 2012-10-26 15:12**MOT test number** 439130402374**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
22 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	22 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-29
Last registration	2024-03-20
Complete history	<a href="#">See info</a>



Registration #1	2009-09-29	8 mi
Registration #2	2012-10-26	21.677 mi
Registration #3	2013-11-27	34.105 mi
Registration #4	2014-06-04	35.611 mi
Registration #5	2015-05-16	43.702 mi
Registration #6	2016-09-05	53.575 mi
Registration #7	2016-09-05	53.575 mi
Registration #8	2018-01-24	64.707 mi
Registration #9	2019-01-25	71.794 mi
Registration #10	2019-01-25	71.794 mi
Registration #11	2019-01-25	71.794 mi
Registration #12	2019-01-25	71.794 mi
Registration #13	2019-01-25	71.794 mi
Registration #14	2019-01-25	71.794 mi
Registration #15	2019-01-25	71.794 mi
Registration #16	2019-01-25	71.794 mi
Registration #17	2019-01-25	71.794 mi
Registration #18	2019-01-25	71.794 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC8245389